



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**Location** 206 203 ABBOTT ST Vancouver

**Cross** [None selected]

**Shift** X

**Incident Type** FIRE - Fire Department Responded Reportable - 1000

**Incident Begin Time** 2022-Apr-11 10:57:38

**Exposure** 0

**Incident Duration** 337 Hrs 48 Mins 44 Secs

### Apparatus

**VAAC01**    **Dispatched**  
**On Route**  
**Onscene**

**Response Time** 0 Hrs 0 Mins 0 Secs

**Delay in Arrival**

**Crew Action** No Fire Action Taken - Unclassified Above

**Remarks**

06/15/2022 09:41:09 User: 12479

Did not attend initial event

Attendees	Position	Last Name	Start Time	End Time
	Officer	Gemmill	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22

**VAAC01**    **Dispatched**  
**On Route**  
**Onscene**

**Response Time** 0 Hrs 0 Mins 0 Secs

**Delay in Arrival**

**Crew Action** No Fire Action Taken - Unclassified Above

**Remarks**

06/15/2022 09:46:02 User: 12479

Did not attend

Attendees	Position	Last Name	Start Time	End Time
	Officer	Gemmill	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAAIR13**    **Dispatched**  
**On Route**  
**Onscene**  
**Remarks**

**Response Time** 0 Hrs 0 Mins 0 Secs

**Delay in Arrival**

**Crew Action** Rehab Support/Decon/Bottle Filling

06/15/2022 09:58:37 User: 12479

Air light duties

Attendees	Position	Last Name	Start Time	End Time
	Driver	Gregory	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22
	Officer	Robertson	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22
	P1	Moran	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22
	P2	Coady	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAB3**    **Dispatched** 2022-Apr-11 10:57:51    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route**    **Delay in Arrival**  
**Onscene**    **Crew Action** Incident Safety Officer

**Remarks**

04/11/2022 21:07:28 User: 06246  
Found L2 on scene Abbott command  
L2 involved in imminent rescue  
on scene with Bat 1  
B3 assigned to ISO  
Kleindienst assigned to run board for operations  
performed 360's  
ensured 2nd means of egress  
notified command of parapet danger  
ensured crews kept proper distance from building  
ensured crews worked safe  
assisted command with various duties

Attendees	Position	Last Name	Start Time	End Time
	Officer	Foellmer	2022-Apr-11 10:57:51	2022-Apr-11 10:59:59
	Officer	Kleindienst	2022-Apr-11 10:57:51	2022-Apr-11 10:59:59

Equipment	QTY	Units	Duration
Misc - Description Required	0	[None Specified]	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAE01</b>	<b>Dispatched</b>	2022-Apr-11 10:57:51	<b>Response Time</b>	0 Hrs 4 Mins 49 Secs
	<b>On Route</b>	2022-Apr-11 10:59:16	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:02:40	<b>Crew Action</b>	Rescue/Ventilation/Extinguish/Salvage/Overhaul

### Remarks

04/11/2022 18:50:14 User: 05112

Reported to command.  
Assigned to perform imminent rescue on bravo /charlie side with 35 ft ladder.  
Rescued two occupants on top floor.  
Advised by bystanders that a occupant jumped out of window and landed on charlie side concrete slab  
Members used mat to bring patient out to BCAS on cardova.  
Members used ground monitor to protect charlie side exposures.  
Members exhausted 5 bottles each during incident.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Deschenes	2022-Apr-11 10:57:51	2022-Apr-11 19:11:03
	Officer	Aylett	2022-Apr-11 10:57:51	2022-Apr-11 19:11:03
	P1	Wiebe	2022-Apr-11 10:57:51	2022-Apr-11 19:11:03
	P2	Fleck	2022-Apr-11 10:57:51	2022-Apr-11 19:11:03

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:Handline-38mm	0	Meters	00:00:00
Hose:Handline-65mm	0	Meters	00:00:00
Hose:150mm	0	Meters	00:00:00
Ladder-over 10m	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
First aid kit	0	Each	00:00:00
Positive Pressure Fan	0	Each	00:00:00
Thermal Imaging Camera	0	Each	00:00:00
Halligan Tool	0	Each	00:00:00



## Vancouver Fire and Rescue Services

### Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAL01**    **Dispatched** 2022-Apr-11 10:57:51    **Response Time** 9 Hrs 22 Mins 17 Secs  
**On Route** 2022-Apr-11 11:01:08    **Delay in Arrival**  
**Onscene** 2022-Apr-11 20:20:08    **Crew Action** Rescue/Ventilation/Extinguish/Salvage/Overhaul

#### Remarks

04/11/2022 22:24:19 User: 12480

VL1 staged at Abbott/ Cordova.  
VL2 and VE1 on scene upon arrival.  
VL1 Staged level one staging.  
Assigned by command as fire attack.  
Gathered all necessary equipment and reported face to face to command.  
Face to face with command, VL 1 re-designated imminent rescue.  
Ran back to VL1  
Repositioned ladder truck to A/D corner of the building.  
Adjusted apparatus positioning for optimum usefulness.  
Noted two occupants leaning out of the fourth window from the north, on the top floor.  
Smoke coming over the heads of the occupants.  
VL1 crew worked as a team to deploy outriggers, and get the aerial ladder up with minimum delay.  
Deployed the aerial to the top floor, and firefighter Ramsden went aloft to assist the building occupants onto the ladder to effect a rescue.  
Assisted one occupant onto the ladder, and assisted to descend.  
FF Makitka then went aloft to assist a second occupant from the window onto the ladder, and assist with descent.  
The two rescued occupants were assisted to BCAS staged at Abbott street and water street.  
Left in care of BCAS.  
VL1 crew continued to provide manpower assistance to other crews on scene.  
After approximately two to three hours, VL1 took an hydrant supply line, and fought the structure fire using the tip monitor the spray water through windows on the top floor.  
Subsequently sprayed water from above onto the roof, with a firefighter at the tip directing the water stream.  
Moved VL1 to the C/D corner at approximately 1800 hrs.  
Continued to use the tip monitor to extinguish hot spots.  
Relieved by VL15.



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

Scene left in care of command.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Dunse	2022-Apr-11 10:57:51	2022-Apr-11 21:42:44
	Officer	Sheasby	2022-Apr-11 10:57:51	2022-Apr-11 21:42:44
	P1	Ramsden	2022-Apr-11 10:57:51	2022-Apr-11 21:42:44
	P2	Mikitka	2022-Apr-11 10:57:51	2022-Apr-11 21:42:44

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:130mm	0	Meters	06:00:00
Hose: Master stream/appliance	0	Meters	05:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	07:00:00

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL02</b>	<b>Dispatched</b>	2022-Apr-11 10:57:51	<b>Response Time</b>	9 Hrs 13 Mins 7 Secs
	<b>On Route</b>	2022-Apr-11 11:00:10	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 20:10:58	<b>Crew Action</b>	Established Command

**Remarks**

04/11/2022 23:15:37 User: 12777

Advised by dispatch that fire escapes on both sides of the building were inoperable while enroute  
 Arrived on scene  
 Established Abbot St command  
 Found smoke coming from multiple windows on the alpha side 2nd and 3rd storey  
 Found multiple residents requiring immediate rescue from 2nd and 3rd storey windows  
 Upgraded fire to working fire and 2nd alarm assignment  
 Tasked crew with setting up ariel for exposure and imminent rescue.  
 Tasked L8 to assist with opening up the fire escape  
 Tasked L1 to setting up aerial for imminent rescue on the A/B corner 3 rd storey.  
 Batt1 arrived on scene and assumed command  
 Tasked with Evacuating 112 Water St of residents.  
 Requested VPD to assist  
 Cleared residents unit by unit and floor to floor with help from building Manager  
 Advised Command that 112 Water St evacuated  
 Reported to staging  
 Retasked to exposure and aerial operations on the alpha side  
 Put out hot spots with aerial  
 Relieved by VL22.  
 Picked up and reloaded hose and assisted setting up VL22 to take our position  
 VL02 - returned to quaters

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Lehwald	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
	Driver	Craven	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
	Officer	Dales	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case # 220017809**      **CAD Event # E221010116**      **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

Officer	Sidhu	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
P1	Malabuyoc	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
P2	Bibby	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
P3	Lewis	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05
P4	Blackburn	2022-Apr-11 10:57:51	2022-Apr-11 21:23:05

### Equipment

	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Axe	0	Each	00:00:00
Hose:Handline-38mm	0	Meters	00:00:00
Hose:Handline-65mm	0	Meters	00:00:00
Hose: Master stream/appliance	0	Meters	00:00:00
Ladder-up to 10m	0	Each	00:00:00
Ladder-over 10m	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Ropes	0	Meters	00:00:00
Positive Pressure Fan	0	Each	00:00:00
Rescue rope Kermantle 1/2"	0	Each	00:00:00
Thermal Imaging Camera	0	Each	00:00:00
Halligan Tool	0	Each	00:00:00

---





# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAL08**    **Dispatched** 2022-Apr-11 10:57:51    **Response Time** 0 Hrs 37 Mins 48 Secs  
**On Route**    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:35:39    **Crew Action** Unclassified

**Remarks**

04/12/2022 07:55:59 User: 15087  
 -Duplicate event  
 -See notes on other call

Attendees	Position	Last Name	Start Time	End Time
	Driver	Holland	2022-Apr-11 10:57:51	2022-Apr-11 16:28:15
	Officer	Nielson	2022-Apr-11 10:57:51	2022-Apr-11 16:28:15
	P1	Butterworth	2022-Apr-11 10:57:51	2022-Apr-11 16:28:15
	P2	Butler	2022-Apr-11 10:57:51	2022-Apr-11 16:28:15
	P4	Zoney	2022-Apr-11 10:57:51	2022-Apr-11 16:28:15



## Vancouver Fire and Rescue Services

### Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAM23**    **Dispatched** 2022-Apr-11 10:57:51    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-11 11:02:11    **Delay in Arrival**  
**Onscene**    **Crew Action** Extinguishment

#### Remarks

04/11/2022 23:47:11 User: 15083

Arrived with L2.

Black smoke showing with multiple imminent rescues on Alpha side.

Tasked Fire Attack.

Pulled 1 3/4" line off L2.

Donned SCBA's.

Stretched line to first floor.

Heavy smoke and some fire on first floor.

Knocked down fires on first floor.

Heavy fire on first floor, Alpha side towards Alpha/Delta corner. Fire was in vaulted atrium area from 1st floor to 3rd floor.

Advanced line to second floor.

Heavy smoke and fire down hallway towards Bravo Charlie corner.

Put water on fire and advanced to atrium area.

Heavy flame and smoke in atrium area.

Used reach of stream to put water on fire.

Advanced line to 3rd floor, heavy smoke and flames.

Went outside to get new SCBA bottles.

Brought nozzle down to second floor on our way out.

Advised Command heading back inside.

Retrieved nozzle from second floor, heavy smoke and flame again from Bravo/Charlie corner.

Darkened down with reach of stream.

Darkened down Alpha Bravo atrium with reach of stream.

Advanced line to 3rd floor, sprayed towards alpha bravo and bravo charlie corners.

Returned to second floor as Bravo Charlie hallway had flared up.

Passed nozzle to Primary search team and exited building.

Reported to rehab/staging.



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

04/12/2022 00:02:26 User: 15083

2.

Tasked as Recon

Checked 112 Water St for Fire Extension/water/smoke damage.

Joined by L2.

Assisted to evacuate residents of 112 Water st.

Requested VPD assistance.

Gathered information on doors that were unsecured or required board up from forcible entry upon evacuation.

Coordinated with vent team to pressurize building and clear out smoke.

Returned to staging.

Tasked to monitor fans in rear alley of 112 water.

Did recon of 112 water.

Determined ventilation no longer required as smoke mostly cleared out.

Assisted to clean up hose and take down ladders.

Released from scene by command.

Decon

RTQ

Attendees	Position	Last Name	Start Time	End Time
	Driver	Lashin	2022-Apr-11 10:57:51	2022-Apr-11 19:40:32
	Officer	Gibson	2022-Apr-11 10:57:51	2022-Apr-11 19:40:32
	P1	Thuss	2022-Apr-11 10:57:51	2022-Apr-11 19:40:32

Equipment	QTY	Units	Duration
Axe	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Halligan Tool	0	Each	00:00:00



## Vancouver Fire and Rescue Services

### Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAB1**    **Dispatched** 2022-Apr-11 11:00:14    **Response Time** 0 Hrs 8 Mins 48 Secs  
**On Route** 2022-Apr-11 11:00:53    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:09:02    **Crew Action** Assumed Command

#### Remarks

04/14/2022 22:08:16 User: 56649

L2 assumed command  
On scene with B3 and B3 shadow  
B3 had tasked initial crews  
Assumed command  
B3 assigned to ISO  
B3 Shadow was in charge of IC Board  
Imminent rescue by E1 on the 2nd floor Bravo Charlie corner using a 35 ft ladder  
Imminent rescue by L2 3rd floor Alpha Bravo corner using aerial  
Imminent rescue, 2 occupants, by L1 on the 3rd floor Alpha Delta corner  
Fire Attack by L1, P6, L7, M23, and RE7  
RIT initially assigned to E2, then transferred to RE4 and RE7  
Back up, L8  
Primary Search by P6, L7, L8  
AC1 assumed command, B1 became Ops  
Exposures covered by E8 (Bravo), E5 (Alpha), L1 Aerial, L3 Aerial, L8 Aerial  
Various crews rotated through operating ground monitors for exterior attacks and exposures  
RE7 crew rescued female through window from 2nd floor Alpha Delta corner using 24 ft ladder  
E2, L2, L8, and RE4 reconned and evacuated 112 Water St  
Rotated crews through rehab and tasks  
Coordinated with AC1 and B3 as well as outside agencies (VPD, BCAS, Hydro, Fortis)  
Updated dispatch on benchmarks  
Relieved temporarily by B3.



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

Attendees	Position	Last Name	Start Time	End Time
	Officer	Greenwood	2022-Apr-11 11:00:14	2022-Apr-11 15:29:29

**VAB3**

<b>Dispatched</b>	2022-Apr-11 11:00:49	<b>Response Time</b>	0 Hrs 2 Mins 36 Secs
<b>On Route</b>	2022-Apr-11 11:01:09	<b>Delay in Arrival</b>	
<b>Onscene</b>	2022-Apr-11 11:03:25	<b>Crew Action</b>	Incident Safety Officer

### Remarks

04/11/2022 21:07:50 User: 06246  
 Found L2 on scene Abbott command  
 L2 involved in imminent rescue  
 on scene with Bat 1  
 B3 assigned to ISO  
 Kleindienst assigned to run board for operations  
 performed 360's  
 ensured 2nd means of egress  
 notified command of parapet danger  
 ensured crews kept proper distance from building  
 ensured crews worked safe  
 assisted command with various duties

Attendees	Position	Last Name	Start Time	End Time
	Officer	Foellmer	2022-Apr-11 11:00:49	2022-Apr-11 17:44:08
	Officer	Kleindienst	2022-Apr-11 11:00:49	2022-Apr-11 17:44:08

Equipment	QTY	Units	Duration
Misc - Description Required	0	[None Specified]	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

**VAINV73**    **Dispatched** 2022-Apr-11 11:02:55    **Response Time** 0 Hrs 4 Mins 5 Secs  
**On Route** 2022-Apr-11 11:02:56    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:07:00    **Crew Action** Investigated - For Cause Determination

**Remarks**

05/08/2022 18:05:58 User: 15084

Refer to LAFC notes

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	La Greca	2022-Apr-11 11:02:55	2022-Apr-11 19:14:22

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Camera	0	Each	00:00:00

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VARE07</b>	<b>Dispatched</b>	2022-Apr-11 11:06:11	<b>Response Time</b>	0 Hrs 5 Mins 44 Secs
	<b>On Route</b>	2022-Apr-11 11:07:57	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:11:55	<b>Crew Action</b>	Rescue/Ventilation/Extinguish/Salvage/Overhaul

### Remarks

04/11/2022 19:36:44 User: 01651

VRE7 laid a line from W Cordova and Cambie st to the alley.  
 Stretched a 2 1/2" line down the alley.  
 Broke line down with a gated wye.  
 Assisted E1 crew to remove a patient from the small alleyway on the Charlie side.  
 Transitional attack on the Bravo and Charlie side.  
 Used a ladder to access the third floor building adjacent to the Charlie side for Fire Attack.  
 Rescued a female patient off the second floor through the window using a ground ladder.  
 Laid a five inch line with Engine 2 to supply Ladder 8.  
 Performed RIT standby on two separate occasions.  
 Entered the second floor Alpha Delta corner to find required documents.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Hooper	2022-Apr-11 11:06:11	2022-Apr-11 19:12:54
	Officer	Pawlak	2022-Apr-11 11:06:11	2022-Apr-11 19:12:54
	P1	Tudge	2022-Apr-11 11:06:11	2022-Apr-11 19:12:54
	P2	Mercer	2022-Apr-11 11:06:11	2022-Apr-11 19:12:54

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Axe	0	Each	00:00:00
Hose:Handline-38mm	0	Meters	00:00:00
Hose:130mm	0	Meters	00:00:00
Camera	0	Each	00:00:00
Ladder-up to 10m	0	Each	00:00:00
Ladder-over 10m	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Thermal Imaging Camera	0	Each	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

<b>Case #</b> 220017809	<b>CAD Event #</b> E221010116	<b>CAD Type</b> RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE
Halligan Tool	0	Each 00:00:00

**VAAIR13**     **Dispatched** 2022-Apr-11 11:06:23     **Response Time** 0 Hrs 14 Mins 17 Secs  
**On Route** 2022-Apr-11 11:11:26     **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:20:40     **Crew Action** Rehab Support/Decon/Bottle Filling

**Remarks**

04/11/2022 20:35:44 User: 09735

Arrived on scene and set up staging at Abbott and Cordova.  
Set up rehab and decon stations.  
Filled SCBA Bottles x 85  
Decontaminated crews as they cycled into rehabilitation  
Kept stations stocked and clean through out the event.  
Officer ran staging/accountability for crews coming in and out of rehab.  
Gave out clean turnout gear x 22.  
Released by BATT 2.  
RTQ.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Gregory	2022-Apr-11 11:06:23	2022-Apr-11 19:27:21
	Officer	Robertson	2022-Apr-11 11:06:23	2022-Apr-11 19:27:21
	P1	Moran	2022-Apr-11 11:06:23	2022-Apr-11 19:27:21
	P2	Coady	2022-Apr-11 11:06:23	2022-Apr-11 19:27:21





# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAE08**    **Dispatched** 2022-Apr-11 11:06:23    **Response Time** 0 Hrs 3 Mins 24 Secs  
**On Route** 2022-Apr-11 11:07:48    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:09:47    **Crew Action** Assisted With Staffing (Not For Medical)

### Remarks

04/12/2022 01:59:40 User: 10891

VE08 designated as Bravo side Exposure team  
VE08 Commanderd the use of VE01 which was closer to the address  
VE08 driver/operator controlled the Pump Panel  
crew extended 2 lengths of 2 1/2" hose for initial Bravo Side Exposure protection  
VE08 also extended another 3 lengths of 2 1/2" hose with an option for two 1 3/8" Handlines  
VE08 worked with VE01 on combating the Bravo side Exposure  
Caution was used with electrical lines still live whilst battling this fire  
Although proper PPE and SCBA were worn  
members were exposed to products of combustion due to the changing wind currents  
Heavy flame and black smoke was resported to Command and informed of our situation  
once Bravo side was kept in control, VE08 reported to Staging  
VE08 was redeployed to provide Delta Side Exposure protection to provide relief to VL03  
VE08 crew was responsible for the VL03 Pump panel and 2 ground monitors  
Lines used to protect the Delta Side Exposure  
the Building to the North side of this building on Water St. was also being protected  
Although proper PPE and SCBA were worn  
members were exposed to products of combustion due to the changing wind currents  
Heavy flame and our situation was resported to Command  
assisted to transfer lines from VL03 to VL01 as VL03 went mechanical  
communication achieved with VL01 and the pump operator regarding our task of Delta side protect  
Members assisted to cleanup hose and assist VL03 to be ready for the Machine Shop  
Once Delta side Exposure was complete  
VE08 members assisted to clean-up hose  
all apparatus on scene wrere loaded properly with hose and equipment and ready for the next Alarm  
VE08 driver assisted to place VL08 in the proper position for arial deployment  
VE08 driver also assisted to locate a hydrant water source with VE02 to lay into VL08  
VE08 was released by VB2  
left the scene in care with AC Morshita and VL01 and VL02



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

04/14/2022 10:17:21 User: 10891

at the start VE08 connected VE01 to the Fire Hydrant on the NE Corner of Abbott St. @ West Cordova

50' and 100' of 5" hose used as supply.

sometime during the Alarm VE08 driver assisted with VE01 driver to relay pump to a repositioned VL02

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Kundarewich	2022-Apr-11 11:06:23	2022-Apr-11 17:57:10
	Officer	De_albuquerque	2022-Apr-11 11:06:23	2022-Apr-11 17:57:10
	P1	Chen	2022-Apr-11 11:06:23	2022-Apr-11 17:57:10
	P2	Thomas	2022-Apr-11 11:06:23	2022-Apr-11 17:57:10

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Thermal Imaging Camera	0	Each	00:00:00

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAE02</b>	<b>Dispatched</b>	2022-Apr-11 11:06:24	<b>Response Time</b>	0 Hrs 5 Mins 12 Secs
	<b>On Route</b>	2022-Apr-11 11:07:25	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:11:36	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

### Remarks

04/11/2022 21:26:41 User: 01575

Tasked as RIT  
 Set up on alpha side and relocated to alpha/delta corner  
 360 of building  
 Reassigned to recon of 112 Water street  
 Checked building with VAM23  
 Checked 112 Water street for smoke, fire and any water damage  
 Ensured no persons in building  
 Reassigned 1 crew member on tip of VAL02 locating hotspots  
 Assisted with clean up  
 Decon  
 Cleared by VAB1

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Dornbierer	2022-Apr-11 11:06:24	2022-Apr-11 18:11:17
	Officer	Leibel	2022-Apr-11 11:06:24	2022-Apr-11 18:11:17
	P1	Kopchia	2022-Apr-11 11:06:24	2022-Apr-11 18:11:17
	P2	Lawson	2022-Apr-11 11:06:24	2022-Apr-11 18:11:17

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Axe	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Thermal Imaging Camera	0	Each	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VACF10</b>	<b>Dispatched</b>	2022-Apr-11 11:07:46	<b>Response Time</b>	2 Hrs 49 Mins 10 Secs
	<b>On Route</b>	2022-Apr-11 11:07:47	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 13:56:56	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

**Remarks**

04/12/2022 12:00:46 User: 10896

Correct on scene time 1110hrs- OS button not pushed

Arrived on scene to support IC.

Requested Mechanic to attend

Liased with Operations and Mechanic for units requiring on site maintenance checks

Ladder 3 placed out of service mechanical once released from scene for aerial inspection due to fire impingment and mechanic issue

Multiple units with Check Engine lights activated and diagnosed by Mechanic

Coordinated 2 reserve units that were to be staffed up by call-out crews

Managed members of Outfitting to ensure reserve units were service ready

Escorted to Fortis for gas shut off

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Hayes	2022-Apr-11 11:07:46	2022-Apr-11 16:54:46



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL03</b>	<b>Dispatched</b>	2022-Apr-11 11:10:40	<b>Response Time</b>	0 Hrs 9 Mins 53 Secs
	<b>On Route</b>	2022-Apr-11 11:14:13	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:20:33	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

### Remarks

04/11/2022 20:17:11 User: 13093

Arrived to find multiple apparatus on scene.  
 Reported to Operations and was asked to lay a line down the Delta side of the building.  
 Used aerial to extinguish hot spots on roof and report of fire conditions.  
 Pulled 2 - 2 1/2" lines and used ground monitors to extinguish 4th floor hot spots.  
 L3 appeared to be overheating.  
 Mechanic requested L3 be shut down and examined for possible damage.  
 Mechanic requested L3 be taken out of service.  
 Operations approved.  
 L3 taken to machine shop for repairs and inspection.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Ward	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	P1	Hassett	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	P1	Macleod	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	P2	Berger	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:Handline-38mm	0	Meters	00:00:00
Hose:Handline-65mm	0	Meters	00:00:00
Hose:150mm	0	Meters	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Thermal Imaging Camera	0	Each	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAP06</b>	<b>Dispatched</b>	2022-Apr-11 11:10:40	<b>Response Time</b>	0 Hrs 10 Mins 8 Secs
	<b>On Route</b>	2022-Apr-11 11:12:37	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:20:48	<b>Crew Action</b>	Extinguishment

### Remarks

04/11/2022 20:23:14 User: 14769

Arrived to find crews on scene.  
 Reported to operations on the alpha side of the structure.  
 Tasked to join L7 as a Primary search group.  
 En route to upper floors search group encountered heavy fire on the 3rd floor.  
 Third floor hallways on the bravo end of the structure were fully engulfed with flames.  
 Primary search (L7) continued on without P6 crew who secured a hose line from the upper floor to attempt to extinguish the fire in the hallways on the 3rd floor and protect means of egress for interior crews.  
 Searched floor 3 at the delta end of the building with 2 members of L7..  
 Low air alarm activated and all members exited building.

04/12/2022 06:49:33 User: 14769

Correction to previous notes.....  
 Heavy fire was encountered on the 2nd floor of residential....commercial considered 1 floor.  
 Primary search was initiated on 2nd floor of building, 1st floor of residential.  
 After exiting building P6 crew was tasked to exposure lines on several occasions on the alpha, bravo and delta sides.  
 Crews exhausted 5-6 bottles of air.

04/14/2022 19:33:49 User: 14769

Further correction to previous notes.....  
 Heavy fire was found on the first floor of residential.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Bouchir	2022-Apr-11 11:10:40	2022-Apr-11 18:39:21
	Officer	Begg	2022-Apr-11 11:10:40	2022-Apr-11 18:39:21
	P1	Zoney	2022-Apr-11 11:10:40	2022-Apr-11 18:39:21
	P2	Peppin	2022-Apr-11 11:10:40	2022-Apr-11 18:39:21



# Vancouver Fire and Rescue Services

## Incident Report

---

<b>Case #</b> 220017809	<b>CAD Event #</b> E221010116	<b>CAD Type</b> RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE
P4	Gonzaga	2022-Apr-11 11:10:40 2022-Apr-11 18:39:21

---

<b>VACF1</b>	<b>Dispatched</b> 2022-Apr-11 11:18:40	<b>Response Time</b> 0 Hrs 0 Mins 1 Secs
	<b>On Route</b> 2022-Apr-11 11:18:40	<b>Delay in Arrival</b>
	<b>Onscene</b> 2022-Apr-11 11:18:41	<b>Crew Action</b> Assisted With Staffing (Not For Medical)

### Remarks

06/15/2022 09:59:31 User: 12479

Assisted with command duties

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Fry	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VACMD4</b>	<b>Dispatched</b>	2022-Apr-11 11:24:16	<b>Response Time</b>	0 Hrs 50 Mins 18 Secs
	<b>On Route</b>	2022-Apr-11 12:14:30	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 12:14:34	<b>Crew Action</b>	RIT Team

### Remarks

04/11/2022 19:02:38 User: 09740

VACMD4 and VARE04 were tasked to transport VACMD4 to the fire scene.  
 Once task was completed VARE04 was tasked to deploy 2 1/2 inch exposure lines.  
 VARE04 was tasked as exposure team on the Alpha side.  
 Following relief of exposure duties VARE04 was designated as Evacuation Team.  
 VARE04 assisted in evacuating 112 Water Street.  
 Once task completed VARE04 was assigned to relieve the exposure team on the Charlie side.  
 VARE04 assigned to staging for rehab.  
 VARE04 redeployed from staging and tasked to relieve RIT.  
 VARE04 designated as RIT on the Alpha Delta corner.  
 VARE04 reassigned to staging for rehab.  
 VARE04 no longer required.  
 Canceled on scene by Command.  
 VARE04 RTQ.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Fenwick	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	Officer	Murray	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	P1	Polonio	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	P2	Yates	2022-Apr-11 11:10:40	2022-Apr-11 16:20:00
	X - Call I	Lucas	2022-Apr-11 12:14:34	2022-Apr-11 17:16:42
	X - Call I	Sleep	2022-Apr-11 12:14:34	2022-Apr-11 17:16:42

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Axe	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00
Halligan Tool	0	Each	00:00:00





# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAMCH87**    **Dispatched** 2022-Apr-11 11:29:37    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-11 11:29:37    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:29:37    **Crew Action** Assisted With Staffing (Not For Medical)

### Remarks

04/12/2022 12:10:52 User: 10896

Mechanic Lorimer was assigned to the fire scene by AAC Hayes  
 Fueled up apparatus  
 diagnosed numerous check engine light activations  
 worked on Ladder 3 that was taken out of service, mechanical failure  
 dealt with numerous concerns from Pump Operators  
 diagnosed and fix electrical issue on Command 4  
 continuous checking of apparatus throughout the incident  
 released by AAC Hayes

04/12/2022 12:18:01 User: 10896

Mechanic Muise was requested to bring foam to scene  
 assisted Mechanic Lorimer on scene with fueling of apparatus and apparatus checks  
 released by AAC Hayes

04/12/2022 12:24:21 User: 10896

FF Scarlett requested to attend by AAC Hayes as driver for Mechanic Muise  
 assisted with supplies  
 FF Scarlett attended the fire scene on four separate occasions to deliver equipment or shuttle members  
 Released by AAC Hayes

Attendees	Position	Last Name	Start Time	End Time
	Driver	Lorimer	2022-Apr-11 11:29:00	2022-Apr-11 16:53:00
	P1	Muise	2022-Apr-11 13:00:00	2022-Apr-11 15:00:00
	P2	Scarlett	2022-Apr-11 13:00:00	2022-Apr-11 16:00:00



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

**VAC87**    **Dispatched** 2022-Apr-11 11:29:37    **Response Time** 0 Hrs 0 Mins 1 Secs  
**On Route** 2022-Apr-11 11:29:37    **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:29:38    **Crew Action** No Action/Cancelled (Not For Medical)

**Remarks**

05/20/2022 07:51:21 User: 10896

This unit does not exist. Mech87 used in place of this unit

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Lorimer	2022-Apr-11 10:57:40	2022-Apr-11 10:57:41

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAE05</b>	<b>Dispatched</b>	2022-Apr-11 11:43:05	<b>Response Time</b>	0 Hrs 8 Mins 51 Secs
	<b>On Route</b>	2022-Apr-11 11:43:49	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 11:51:56	<b>Crew Action</b>	Extinguishment

### Remarks

04/11/2022 19:00:53 User: 09718

VAE05 arrived on 4th alarm assignment to staging.  
 Tasked to man handline's and ground monitors on alpha side of building.  
 Rehabed.  
 Tasked back to handline's and ground monitors on alpha side.  
 Assisted with clean up of equipment.  
 Cleared by command.  
 Left in care of on scene crews.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Heriot	2022-Apr-11 11:43:05	2022-Apr-11 16:52:09
	Officer	Ballard	2022-Apr-11 11:43:05	2022-Apr-11 16:52:09
	P1	Bird	2022-Apr-11 11:43:05	2022-Apr-11 16:52:09
	P2	Isherwood	2022-Apr-11 11:43:05	2022-Apr-11 16:52:09
	P4	May	2022-Apr-11 11:43:05	2022-Apr-11 16:52:09

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:Handline-65mm	0	Meters	00:00:00
Hose: Master stream/appliance	0	Meters	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	05:00:00
Misc - Desription Required	0	[None Specified]	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809      **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

**VAE19**      **Dispatched** 2022-Apr-11 11:43:05      **Response Time** 0 Hrs 9 Mins 0 Secs  
**On Route** 2022-Apr-11 11:44:46      **Delay in Arrival**  
**Onscene** 2022-Apr-11 11:52:05      **Crew Action** Extinguishment/Salvage/Overhaul

**Remarks**

04/11/2022 17:14:54 User: 10907

Reported to staging  
Tasked out to work ground monitors  
Returned to staging  
Tasked out to pressurize 112 Water St, known as VENT  
Cleared by command.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Laverock	2022-Apr-11 11:43:05	2022-Apr-11 16:18:40
	Officer	Ryan	2022-Apr-11 11:43:05	2022-Apr-11 16:18:40
	P1	Macdonald	2022-Apr-11 11:43:05	2022-Apr-11 16:18:40
	P2	Manning	2022-Apr-11 11:43:05	2022-Apr-11 16:18:40

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL07</b>	<b>Dispatched</b>	2022-Apr-11 12:10:42	<b>Response Time</b>	0 Hrs 0 Mins 1 Secs
	<b>On Route</b>	2022-Apr-11 12:10:42	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 12:10:43	<b>Crew Action</b>	Search Primary
	<b>Remarks</b>			

04/11/2022 18:23:45 User: 11655

Reported to incident command on A side of building  
 Tasked as primary search group with P6  
 Initiated primary search on 2nd floor north side  
 Crews encountered heavy fire conditions in hallways on south side of building  
 Requested additional fire attack crews for 2nd floor  
 Fire attack crew from 3rd floor moved hoseline down to assist with fire attack P6 took over handline  
 Completed primary search on north side and updated command  
 Assisted P6 with hoseline and fire attack on 2nd floor  
 Exited building and reported to command  
 Re tasked as Exp team on AB corner  
 Cleared from incident by AC1

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Lamb	2022-Apr-11 12:10:42	2022-Apr-11 15:55:58
	Officer	Lees	2022-Apr-11 12:10:42	2022-Apr-11 15:55:58
	P1	Caddell	2022-Apr-11 12:10:42	2022-Apr-11 15:55:58
	P2	Gunster	2022-Apr-11 12:10:42	2022-Apr-11 15:55:58

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
SCBA - 30 or 45 minute bottle	0	Bottle	04:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VACF2</b>	<b>Dispatched</b>	2022-Apr-11 12:36:36	<b>Response Time</b>	0 Hrs 0 Mins 1 Secs
	<b>On Route</b>	2022-Apr-11 12:36:36	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 12:36:37	<b>Crew Action</b>	Unclassified

**Remarks**

05/11/2022 08:15:24 User: 07009

Staffed Command unit  
Assisted with logistics

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Moore	2022-Apr-11 12:36:36	2022-Apr-11 17:13:25

<b>VAINV75</b>	<b>Dispatched</b>	2022-Apr-11 12:41:07	<b>Response Time</b>	0 Hrs 7 Mins 39 Secs
	<b>On Route</b>	2022-Apr-11 12:41:08	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 12:48:46	<b>Crew Action</b>	Investigated - For Cause Determination

**Remarks**

04/27/2022 14:12:44 User: 12479

Refer to LAFC notes

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Schmidt	2022-Apr-11 10:57:38	2022-Apr-14 14:59:21



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VACF15**    **Dispatched** 2022-Apr-11 14:21:49    **Response Time** 0 Hrs 0 Mins 1 Secs  
**On Route** 2022-Apr-11 14:21:49    **Delay in Arrival**  
**Onscene** 2022-Apr-11 14:21:50    **Crew Action** Assisted With Staffing (Not For Medical)

**Remarks**

06/15/2022 10:15:51 User: 12479  
Vacum up water in parkades

Attendees	Position	Last Name	Start Time	End Time
	Officer	Schmidt	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22

**VAB2**    **Dispatched** 2022-Apr-11 14:30:31    **Response Time** 0 Hrs 13 Mins 12 Secs  
**On Route** 2022-Apr-11 14:30:32    **Delay in Arrival**  
**Onscene** 2022-Apr-11 14:43:43    **Crew Action** Established Command

**Remarks**

06/15/2022 09:52:05 User: 12479  
Established command duties

Attendees	Position	Last Name	Start Time	End Time
	Officer	Sojka	2022-Apr-11 14:30:31	2022-Apr-11 19:52:14



## Vancouver Fire and Rescue Services

### Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAL08**    **Dispatched** 2022-Apr-11 16:30:12    **Response Time** 0 Hrs 0 Mins 4 Secs  
**On Route**    **Delay in Arrival**  
**Onscene** 2022-Apr-11 16:30:16    **Crew Action** Rescue/Ventilation/Extinguish/Salvage/Overhaul

#### Remarks

04/12/2022 07:37:40 User: 15087

- On scene heavy smoke coming from multiple third story windows on the Alpha side of building
- Assisted residents exiting the building on the Delta side of structure from the fire escape
- The padlocked hatch was opened using bolt cutters
- Two residents used building metal ladder to climb down building
- IC designated VL08 crew as Back up to Fire Attack crew in building with charged 45 mm handline on the Alpha side of building
- Assisted crew as Back up to cool fire in windows on Alpha side of building
- IC redesignate VL08 crew as Primary Search on second floor of building
- Updated from VE06 crew exiting building as Primary Search crew Lt. Begg, AJ
- I was told there was extremely wet conditions from aerial monitors on second floor on Bravo side
- Also heavy fire activity on Bravo side on second floor of building
- VL08 crew hauled 1 3/4 inch (45 mm) drained and flaked the line on the second floor
- Then charged the handline
- Began door to door search on the Delta side of second floor
- VL08 crew search approximately 10 rooms before IC radioed all crews to exit the building
- Left the line in the building and reported to ISO officer and IC that crew of four members exited the building and no persons found on Delta side of second floor
- Moved VL08 in position to use monitor on aerial
- Rehab with four members
- FF Holland, K went to VL08 to use the aerial monitor on the fire
- Continued with three member crew and IC designated crew as Recon at 112 Water St.
- No keys for access to rooms with metal doors in side building and exited building to get contact with keys
- Redesignated as Exposure crew on Delta side of building with 2 1/2 inch (65mm) handline
- Assisted crews to pick up hose and ladders
- VL08 crew got clean gear at clothing wagon
- Cleared by IC Sokja, A and returned to hall





# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

-  
-

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Holland	2022-Apr-11 16:30:12	2022-Apr-11 18:09:06
	Officer	Nielson	2022-Apr-11 16:30:12	2022-Apr-11 18:09:06
	P1	Butterworth	2022-Apr-11 16:30:12	2022-Apr-11 18:09:06
	P2	Butler	2022-Apr-11 16:30:12	2022-Apr-11 18:09:06
	P4	Zoney	2022-Apr-11 16:30:12	2022-Apr-11 18:09:06

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:Handline-38mm	0	Meters	00:00:00
Hose:Handline-65mm	0	Meters	00:00:00
Hose:130mm	0	Meters	00:00:00
Ladder-over 10m	0	Each	00:00:00
Overhaul Tools	0	Each	00:00:00
Thermal Imaging Camera	0	Each	00:00:00

---



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

**VAB1**    **Dispatched** 2022-Apr-11 18:37:05    **Response Time** 0 Hrs 6 Mins 43 Secs  
**On Route** 2022-Apr-11 18:37:13    **Delay in Arrival**  
**Onscene** 2022-Apr-11 18:43:48    **Crew Action** Assumed Command

**Remarks**

04/14/2022 22:14:04 User: 56649

Returned to scene  
Re assumed Ops from B3  
Crews were strictly defensive at this point  
Aerial defensive attacks  
Coordinated plan with B3 to have various ladder crews rotate fire watch  
Communicated plan to respective crews and dispatch  
Left scene in charge of L22.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Greenwood	2022-Apr-11 18:37:05	2022-Apr-11 21:45:13

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VATW10**    **Dispatched** 2022-Apr-11 19:01:48    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-11 19:01:49    **Delay in Arrival**  
**Onscene**    **Crew Action** No Action/Cancelled (Not For Medical)

**Remarks**

04/11/2022 20:57:22 User: 12477

T10 responded to event as instructed-reported for relief 19:30  
Advised command T10 ETA 10 min inbound to scene at 19:20  
Dispatch advise T10 to return to quarters 19:28  
Complied

Attendees	Position	Last Name	Start Time	End Time
	Driver	Nicholson	2022-Apr-11 19:01:48	2022-Apr-11 19:33:39
	Driver	Steele	2022-Apr-11 19:01:48	2022-Apr-11 19:33:39
	P1	Grieve	2022-Apr-11 19:01:48	2022-Apr-11 19:33:39
	P2	Wolff	2022-Apr-11 19:01:48	2022-Apr-11 19:33:39



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL22</b>	<b>Dispatched</b>	2022-Apr-11 19:25:38	<b>Response Time</b>	0 Hrs 13 Mins 37 Secs
	<b>On Route</b>	2022-Apr-11 19:25:39	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 19:39:15	<b>Crew Action</b>	Overhaul

**Remarks**

04/11/2022 23:09:17 User: 14561

Found Ladder 2 on scene.  
 Relieved Ladder 2 of its position on the fireground.  
 Deployed Aerial to the Alpha side of the building.  
 Deployed 2.5 in. ground monitor at the alpha bravo corner.  
 Sent members to the tip of the aerial to monitor conditions with a TIC camera.  
 No changes to report at the time.  
 Relieved by Ladder 7.  
 Returned to quarters.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Waloszek	2022-Apr-11 19:25:38	2022-Apr-11 22:36:02
	Officer	Pereira	2022-Apr-11 19:25:38	2022-Apr-11 22:36:02
	P1	Swantje	2022-Apr-11 19:25:38	2022-Apr-11 22:36:02
	P2	Mollica	2022-Apr-11 19:25:38	2022-Apr-11 22:36:02
	P3	Lynch	2022-Apr-11 19:25:38	2022-Apr-11 22:36:02

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Hose:Handline-65mm	0	Meters	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL15</b>	<b>Dispatched</b>	2022-Apr-11 19:59:58	<b>Response Time</b>	0 Hrs 0 Mins 1 Secs
	<b>On Route</b>	2022-Apr-11 19:59:58	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 19:59:59	<b>Crew Action</b>	No Action/Cancelled (Not For Medical)

**Remarks**

05/08/2022 10:14:57 User: 09718  
Cancelled en route by dispatch via radio  
AOR

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Anderson	2022-Apr-11 19:59:58	2022-Apr-11 22:17:54
	Officer	Anderson	2022-Apr-11 19:59:58	2022-Apr-11 22:17:54
	P1	Dubbert	2022-Apr-11 19:59:58	2022-Apr-11 22:17:54
	P1	Miller	2022-Apr-11 19:59:58	2022-Apr-11 22:17:54

<b>VAM23</b>	<b>Dispatched</b>	2022-Apr-11 20:01:51	<b>Response Time</b>	0 Hrs 9 Mins 15 Secs
	<b>On Route</b>	2022-Apr-11 20:08:32	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 20:11:06	<b>Crew Action</b>	Unclassified

**Remarks**

04/11/2022 21:18:07 User: 15083  
Called back to scene to review suites that required board up and door repairs in 112 Water St.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Gibson	2022-Apr-11 20:01:51	2022-Apr-11 20:24:15
	P1	Lashin	2022-Apr-11 20:01:51	2022-Apr-11 20:24:15
	P1	Thuss	2022-Apr-11 20:01:51	2022-Apr-11 20:24:15



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAL05**    **Dispatched** 2022-Apr-11 21:30:03    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-11 21:30:04    **Delay in Arrival**  
**Onscene**    **Crew Action** Standby - Firewatch

**Remarks**

04/12/2022 01:52:18 User: 07237

VL05 relieved VL15 of Fire Watch duties  
VL05 hooked into existing 5" LDH supply line from hydrant and deployed aerial to appropriate spot above affected structure and monitored scene of fire on upper floor for hot spots  
VL05 relieved at the scene by VL08  
Exchanged 150' of 5" LDH with VL08  
Scene left in care of VL08  
VL05 RTQ

Attendees	Position	Last Name	Start Time	End Time
	Driver	Bennett	2022-Apr-11 21:30:03	2022-Apr-12 01:11:02
	Officer	Chamberland	2022-Apr-11 21:30:03	2022-Apr-12 01:11:02
	P1	May	2022-Apr-11 10:57:38	2022-Apr-25 12:46:22
	P2	Nikolai	2022-Apr-11 21:30:03	2022-Apr-12 01:11:02
	P3	Isherwood	2022-Apr-11 10:57:38	2022-Apr-12 12:46:22



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL07</b>	<b>Dispatched</b>	2022-Apr-11 21:57:19	<b>Response Time</b>	0 Hrs 7 Mins 34 Secs
	<b>On Route</b>	2022-Apr-11 21:57:20	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-11 22:04:53	<b>Crew Action</b>	Search Primary

**Remarks**

06/16/2022 08:42:36 User: 12479

Reported to incident command on A side of building  
 Tasked as primary search group with P6  
 Initiated primary search on 2nd floor north side  
 Crews encountered heavy fire conditions in hallways on south side of building  
 Requested additional fire attack crews for 2nd floor  
 Fire attack crew from 3rd floor moved hoseline down to assist with fire attack P6 took over handline  
 Completed primary search on north side and updated command  
 Assisted P6 with hoseline and fire attack on 2nd floor  
 Exited building and reported to command  
 Re tasked as Exp team on AB corner  
 Cleared from incident by AC1

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Lamb	2022-Apr-11 21:57:19	2022-Apr-12 00:31:21
	Officer	Lees	2022-Apr-11 21:57:19	2022-Apr-12 00:31:21
	P1	Caddell	2022-Apr-11 21:57:19	2022-Apr-12 00:31:21
	P2	Gunster	2022-Apr-11 21:57:19	2022-Apr-12 00:31:21



# Vancouver Fire and Rescue Services

## Incident Report

---

**Case #** 220017809      **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

**VAB2**      **Dispatched** 2022-Apr-11 22:51:12      **Response Time** 0 Hrs 16 Mins 15 Secs  
**On Route** 2022-Apr-11 22:51:13      **Delay in Arrival**  
**Onscene** 2022-Apr-11 23:07:27      **Crew Action** Established Command

**Remarks**

06/16/2022 08:56:26 User: 12479

Established Command

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Officer	Sojka	2022-Apr-11 22:51:12	2022-Apr-11 23:43:21

---





# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL08</b>	<b>Dispatched</b>	2022-Apr-12 00:51:18	<b>Response Time</b>	0 Hrs 20 Mins 16 Secs
	<b>On Route</b>	2022-Apr-12 00:51:19	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-12 01:11:34	<b>Crew Action</b>	Unclassified
	<b>Remarks</b>			

04/12/2022 07:49:34 User: 15087

- VL08 crew relieved VL05 crew at 01:00 for firewatch and told by BC2 Sokja, A
- Connected to hydrate and set up aerial ladder of VL08
- Continued to check 203 Abbott St. building with TIC camera and do 360 of building
- No hot spots found
- Relieved by VL18 crew at 04:00
- Updated dispatch via radio
- Returned to hall

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Holland	2022-Apr-12 00:51:18	2022-Apr-12 04:23:55
	Officer	Nielson	2022-Apr-12 00:51:18	2022-Apr-12 04:23:55
	P1	Butler	2022-Apr-12 00:51:18	2022-Apr-12 04:23:55
	P2	Chen	2022-Apr-12 00:51:18	2022-Apr-12 04:23:55

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Thermal Imaging Camera	0	Each	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL18</b>	<b>Dispatched</b>	2022-Apr-12 03:44:03	<b>Response Time</b>	0 Hrs 14 Mins 6 Secs
	<b>On Route</b>	2022-Apr-12 03:44:04	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-12 03:58:09	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

**Remarks**

04/12/2022 08:21:11 User: 15520

Routine response  
 Relieved VL08 on scene  
 Fire Watch from 0400-0730  
 Staged aerial and looked for hotshots every 30 mins from tip of VL18  
 Left in care of VT10  
 RTQ

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Turner	2022-Apr-12 03:44:03	2022-Apr-12 07:49:35
	Officer	Baxter	2022-Apr-12 03:44:03	2022-Apr-12 07:49:35
	P2	Macgregor	2022-Apr-12 03:44:03	2022-Apr-12 07:49:35
	P2	Bolina	2022-Apr-12 03:44:03	2022-Apr-12 07:49:35
	P3	Peck	2022-Apr-12 03:44:03	2022-Apr-12 07:49:35



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VATW10</b>	<b>Dispatched</b>	2022-Apr-12 07:04:28	<b>Response Time</b>	0 Hrs 29 Mins 38 Secs
	<b>On Route</b>	2022-Apr-12 07:04:29	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-12 07:34:06	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

**Remarks**

04/12/2022 10:49:12 User: 13084

Found Chief's Fry, Connelly and Boone on scene.  
Tasked with setting up tower on Bravo side of building for an Engineer and Chief Fry to go up and inspect the building from above.  
Remained O/S as fire watch until we were relieved by L7.

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Kingston	2022-Apr-12 07:04:28	2022-Apr-12 10:01:46
	Officer	Bourdeaud'huy	2022-Apr-12 07:04:28	2022-Apr-12 10:01:46
	P1	Walsh	2022-Apr-12 07:04:28	2022-Apr-12 10:01:46
	P2	Amyotte	2022-Apr-12 07:04:28	2022-Apr-12 10:01:46

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Misc - Description Required	0	[None Specified]	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAM02**    **Dispatched** 2022-Apr-12 08:05:19    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route**  
**Onscene**    **Delay in Arrival**  
**Crew Action** Unclassified

**Remarks**

06/16/2022 09:46:11 User: 12479  
Fire watch duties

Attendees	Position	Last Name	Start Time	End Time
	Driver	Reed	2022-Apr-12 08:05:19	2022-Apr-12 08:11:49
	Officer	Sandberg	2022-Apr-12 08:05:19	2022-Apr-12 08:11:49
	P1	James	2022-Apr-12 08:05:19	2022-Apr-12 08:11:49

**VAM02**    **Dispatched** 2022-Apr-12 08:11:51    **Response Time** 0 Hrs 8 Mins 21 Secs  
**On Route** 2022-Apr-12 08:16:51    **Delay in Arrival**  
**Onscene** 2022-Apr-12 08:20:12    **Crew Action** Unclassified

**Remarks**

06/16/2022 09:47:27 User: 12479  
Fire watch duties

Attendees	Position	Last Name	Start Time	End Time
	Driver	Reed	2022-Apr-12 08:11:51	2022-Apr-12 09:02:45
	Officer	Sandberg	2022-Apr-12 08:11:51	2022-Apr-12 09:02:45
	P1	James	2022-Apr-12 08:11:51	2022-Apr-12 09:02:45



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAINV73**    **Dispatched** 2022-Apr-12 08:13:29    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-12 08:13:30    **Delay in Arrival**  
**Onscene**    **Crew Action** Investigated - For Cause Determination

**Remarks**

05/08/2022 18:12:35 User: 15084

See LAFC notes

Attendees	Position	Last Name	Start Time	End Time
	Officer	La Greca	2022-Apr-12 08:13:29	2022-Apr-12 08:36:05
	Officer	Cook	2022-Apr-12 08:13:29	2022-Apr-12 08:36:05

Equipment	QTY	Units	Duration
Camera	0	Each	00:00:00

**VAL07**    **Dispatched** 2022-Apr-12 09:27:26    **Response Time** 0 Hrs 16 Mins 51 Secs  
**On Route** 2022-Apr-12 09:27:27    **Delay in Arrival**  
**Onscene** 2022-Apr-12 09:44:17    **Crew Action** Unclassified

**Remarks**

04/12/2022 11:58:27 User: 14771

Relieved VT10 for fire watch  
Assisted Board up crew with access  
LIC VL03

Attendees	Position	Last Name	Start Time	End Time
	Driver	Sherriff	2022-Apr-12 09:27:26	2022-Apr-12 11:34:27
	Officer	Hastings	2022-Apr-12 09:27:26	2022-Apr-12 11:34:27
	P1	Casano	2022-Apr-12 09:27:26	2022-Apr-12 11:34:27
	P2	Jones	2022-Apr-12 09:27:26	2022-Apr-12 11:34:27



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VARE04</b>	<b>Dispatched</b>	2022-Apr-12 10:02:23	<b>Response Time</b>	0 Hrs 0 Mins 1 Secs
	<b>On Route</b>	2022-Apr-12 10:02:23	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-12 10:02:24	<b>Crew Action</b>	RIT Team

### Remarks

04/12/2022 14:12:45 User: 09740

VACMD4 and VARE04 were tasked to transport VACMD4 to the fire scene.  
 Once task was completed VARE04 was tasked to deploy 2 1/2 inch exposure lines.  
 VARE04 was tasked as exposure team on the Alpha side.  
 Following relief of exposure duties VARE04 was designated as Evacuation Team.  
 VARE04 assisted in evacuating 112 Water Street.  
 Once task completed VARE04 was assigned to relieve the exposure team on the Charlie side.  
 VARE04 assigned to staging for rehab.  
 VARE04 redeployed from staging and tasked to relieve RIT.  
 VARE04 designated as RIT on the Alpha Delta corner.  
 VARE04 reassigned to staging for rehab.  
 VARE04 no longer required.  
 Canceled on scene by Command.  
 VARE04 RTQ

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Mosher	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	Driver	Yates	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	Officer	Cap	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	Officer	Murray	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	P1	Polonio	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	P1	Wilgosh	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	P2	Cameron	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25
	P2	Fenwick	2022-Apr-12 10:02:23	2022-Apr-12 10:02:25

<b>Equipment</b>	<b>QTY</b>	<b>Units</b>	<b>Duration</b>
Axe	0	Each	00:00:00
SCBA - 30 or 45 minute bottle	0	Bottle	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

---

<b>Case #</b> 220017809	<b>CAD Event #</b> E221010116	<b>CAD Type</b> RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE
Halligan Tool	0	Each 00:00:00

---

<b>VAL03</b>	<b>Dispatched</b> 2022-Apr-12 11:06:24	<b>Response Time</b> 0 Hrs 30 Mins 25 Secs
	<b>On Route</b> 2022-Apr-12 11:06:25	<b>Delay in Arrival</b>
	<b>Onscene</b> 2022-Apr-12 11:36:49	<b>Crew Action</b> Unclassified

### Remarks

06/16/2022 08:49:01 User: 12479  
Fire Watch duties

Attendees	Position	Last Name	Start Time	End Time
	Driver	Johnston	2022-Apr-12 11:06:24	2022-Apr-12 13:59:31
	Officer	Mcnutt	2022-Apr-12 11:06:24	2022-Apr-12 13:59:31
	P1	Murphy	2022-Apr-12 11:06:24	2022-Apr-12 13:59:31
	P2	Bernard	2022-Apr-12 11:06:24	2022-Apr-12 13:59:31

---



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>VAL05</b>	<b>Dispatched</b>	2022-Apr-12 13:17:47	<b>Response Time</b>	0 Hrs 30 Mins 46 Secs
	<b>On Route</b>	2022-Apr-12 13:17:48	<b>Delay in Arrival</b>	
	<b>Onscene</b>	2022-Apr-12 13:48:33	<b>Crew Action</b>	Assisted With Staffing (Not For Medical)

**Remarks**

04/12/2022 22:10:01 User: 12773

VL05 responded routine to relieve VL03 on scene for fire watch  
 Staged at Water and Abbott St.  
 At 15:30 received a call from A/C Bertuzzi to stand down fire watch  
 Upon receiving keys from VL03 we dropped them off to the on duty F/I Schmidt at #1 Hall  
 Before leaving the scene we secured all the doors but one to the cafe by the alley  
 Notified VPD on scene that scene was locked down except for one business  
 No further assistance required  
 Left in care of VPD on scene

<b>Attendees</b>	<b>Position</b>	<b>Last Name</b>	<b>Start Time</b>	<b>End Time</b>
	Driver	Fahy	2022-Apr-12 13:17:47	2022-Apr-12 15:37:29
	Officer	Korstrom	2022-Apr-12 13:17:47	2022-Apr-12 15:37:29
	P1	Skinner	2022-Apr-12 13:17:47	2022-Apr-12 15:37:29
	P2	Pidhirniak	2022-Apr-12 13:17:47	2022-Apr-12 15:37:29
	P4	Kamer	2022-Apr-12 13:17:47	2022-Apr-12 15:37:29





# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAL15**    **Dispatched** 2022-Apr-12 15:07:38    **Response Time** 0 Hrs 0 Mins 0 Secs  
**On Route** 2022-Apr-12 15:07:39    **Delay in Arrival**  
**Onscene**    **Crew Action** No Action/Cancelled (Not For Medical)

**Remarks**

04/12/2022 18:58:49 User: 14471  
-cancelled en route to release firewatch crew

Attendees	Position	Last Name	Start Time	End Time
	Driver	Kuyer	2022-Apr-12 15:07:38	2022-Apr-12 15:20:36
	Officer	Shalist	2022-Apr-12 15:07:38	2022-Apr-12 15:20:36
	P1	Ekman	2022-Apr-12 15:07:38	2022-Apr-12 15:20:36
	P2	Youngman	2022-Apr-12 15:07:38	2022-Apr-12 15:20:36

**VAINV73**    **Dispatched** 2022-Apr-14 13:54:56    **Response Time** 0 Hrs 0 Mins 15 Secs  
**On Route**    **Delay in Arrival**  
**Onscene** 2022-Apr-14 13:55:11    **Crew Action** Investigated - For Cause Determination

**Remarks**

05/08/2022 18:17:20 User: 15084  
Refer to LAFC notes

Attendees	Position	Last Name	Start Time	End Time
	Officer	La Greca	2022-Apr-14 13:54:56	2022-Apr-14 14:59:21

Equipment	QTY	Units	Duration
Camera	0	Each	00:00:00



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**VAINV73**    **Dispatched** 2022-Apr-25 12:13:25    **Response Time** 0 Hrs 0 Mins 1 Secs  
**On Route** 2022-Apr-25 12:13:25    **Delay in Arrival**  
**Onscene** 2022-Apr-25 12:13:26    **Crew Action** Investigated - For Cause Determination

### Remarks

06/12/2022 14:01:37 User: 15084  
 Interview with s.22(1), the Arco Hotel.

Attendees	Position	Last Name	Start Time	End Time
	Officer	La Greca	2022-Apr-25 12:13:25	2022-Apr-25 12:46:22

Equipment	QTY	Units	Duration
Camera	0	Each	00:00:00

### Other Agencies

	Reference #	Name
Private - Not listed above	s.22(1)	s.22(1)
Police - VPD	22-60347	Det. Jennifer Tang
Utilities - Hydro		
Provincial - Public Safety and Solicitor General	2022-5054-0171	
Provincial - BC Ambulance		Jamie Rodgers
Municipal - Building Inspector		Saul Schwebs

### Fire Report



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**Report Type** Structure

**AC** 3000 Extinguished by fire department

**WildLand Interface?**

**AD** 0000 Cannot be determined

**Number of Occupants** 0

**AL** 1000 911

**AO** 7700 Ignorance of hazard (Note: if illegal operations, classify as 9950)

**BH** 0040 4 Stories above grade

**EX** 4800 Portable/fixed water deluge/master stream set

**FH** 4000 Direct flame

**FS** 1000 Career fire department only

**FU** 1000 Solid fuel (e.g. coal, wood, pellets, paper or waste used for lighting or incidental burning)

**GC** 0009 General construction - unclassified (describe)

**GF** 3000 501 to 1000 m<sup>2</sup> (5383 - 10764 ft<sup>2</sup>)

**ID** 7000 Visual sighting or other means of personal detection (e.g. smell)

**IG** 7400 "Open" Flame - Candle

**IN** 1000 Fire - fire department attended

**LV** 4000 2nd storey or over 3m to 6m (10ft to 20ft) above grade

**MF** 4000 Extinguisher only

**MI** 2500 Mattress (includes hide-a-bed mattress, box spring)

**OA** 2100 Sleeping - under 5 occupants (includes patients room, bedroom, cell, lockup)

**OF** 1000 Public hydrant protection & fire department

**PC** 3900 Residential - with business/mercantile, up to 3 stories

**PR** 3390 Rooming, boarding, lodging house - unclassified (describe)

**SD** 0000 Cannot be determined

**SP** 1000 Complete sprinkler protection - supervised (on-site or off-site)

**XD** 5000 Confined to building of origin

**XF** 5000 Confined to building of origin

**YC** 0020 (1920 or before)

### Names



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**Contact Type** Business Occupant

**Name** s.22(1)

**Business Name** Atira Property Management

**Telephone** s.22(1) 8

**Address** 405 Powell St  
Vancouver  
V6A1G7

**Building Value** 0

**Building Loss** 0

**Contents Value** 0

**Contents Loss** 0

**Insurance Company**

**Insurance Adjuster**

**Claim Number**

**Policy Num**

**Contact Type** Business Owner

**Name** s.22(1)

**Business Name** Bruce Eyewear

**Telephone**

**Address** 219 Abbott St.  
Vancouver

**Building Value** 500000

**Building Loss** 500000

**Contents Value** 0

**Contents Loss** 0

**Insurance Company** F/I Estimate

**Insurance Adjuster**

**Claim Number**

**Policy Num**

### Remarks

**Title** email  
vuksic.nada@gmail.com

**Contact Type** Business Owner

**Name** s.22(1)

**Business Name** Gowon Cafe

**Telephone**

**Address**

**Building Value** 500000

**Building Loss** 500000

**Contents Value** 0

**Contents Loss** 0

**Insurance Company** F/I Estimate

**Insurance Adjuster**

**Claim Number**

**Policy Num**

**Contact Type** Business Owner

**Building Value** 500000



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

<b>Name</b>	s.22(1)	<b>Building Loss</b>	500000
<b>Business Name</b>	Lemongrass House	<b>Contents Value</b>	0
<b>Telephone</b>		<b>Contents Loss</b>	0
<b>Address</b>	209 Abbott St. Vancouver	<b>Insurance Company</b>	F/I Estimate
		<b>Insurance Adjuster</b>	
		<b>Claim Number</b>	
		<b>Policy Num</b>	

### Remarks

**Title** email  
s.22(1) m

<b>Contact Type</b>	Business Owner	<b>Building Value</b>	400000
<b>Name</b>	s.22(1)	<b>Building Loss</b>	400000
<b>Business Name</b>	Nika	<b>Contents Value</b>	0
<b>Telephone</b>		<b>Contents Loss</b>	0
<b>Address</b>	205 Abbott St. Vancouver	<b>Insurance Company</b>	F/I Estimate
		<b>Insurance Adjuster</b>	
		<b>Claim Number</b>	
		<b>Policy Num</b>	

### Remarks

**Title** email  
s.22(1)

<b>Contact Type</b>	Business Owner	<b>Building Value</b>	500000
<b>Name</b>	s.22(1)	<b>Building Loss</b>	500000
<b>Business Name</b>	Roldorf & Co.	<b>Contents Value</b>	0
<b>Telephone</b>	s.22(1)	<b>Contents Loss</b>	0
<b>Address</b>	207 Abbott St. Vancouver	<b>Insurance Company</b>	F/I Estimate
		<b>Insurance Adjuster</b>	



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

**Contact Type** Business Owner  
**Name** s.22(1)  
**Business Name** The Flying Pig  
**Telephone** s.22(1)  
**Address** 102 Water St.  
 Vancouver

**Contact Type** Owner  
**Name** s.22(1)  
**Business Name**  
**Telephone**  
**Address** s.22(1)

**Claim Number**  
**Policy Num**  
**Building Value** 500000  
**Building Loss** 500000  
**Contents Value** 0  
**Contents Loss** 0  
**Insurance Company** F/I Estimate  
**Insurance Adjuster**  
**Claim Number**  
**Policy Num**  
**Building Value** 20000000  
**Building Loss** 20000000  
**Contents Value** 0  
**Contents Loss** 0  
**Insurance Company** F/I Estimate  
**Insurance Adjuster**  
**Claim Number**  
**Policy Num**

### External Remarks

**Title** VFRS# 6183  
 INC# 22-0017809  
 203 Abbott Street  
 April 11/2022  
 1057hrs  
 VPD# 22-54132

VAINV73 responded to 203 Abbott for a structure fire. B/C Greenwood, A. in command.

203 Abbott Street is a 4-storey, type 3 construction, SRO with seven businesses on the ground level and a sub level basement. 203 Abbott is a secondary address, the primary address is 102 Water St. This



## Vancouver Fire and Rescue Services

### Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

building was constructed in 1904. Fire protection systems included portable fire extinguishers, fire alarm, automatic fire sprinklers and fire escapes.

For clarity, the four upper levels will be described as the Ground, 1st, 2nd, and 3rd floors. There was a previous fire at this building in unit #222 on April 8th 2022, Inc#22-0017364. 203 Abbott was under a 24 hr. fire watch order. There was a notice of violation issued to have fire sprinklers and smoke detectors serviced. Royal City Fire was contacted by building staff on the morning of April 11th and were scheduled to arrive sometime that day. The automatic sprinkler system was shut off at the time of this fire and the fire alarm system was not in service.

Lt. Sidhu, G. from VL02 was first on scene. Lt. Sidhu reported that upon their arrival, there were 2 people requiring imminent rescue from the 3rd floor window on A/D side. VE01 fire crews were setting up hose lines on the bravo side. The crew opened an exterior door leading to a small alley on the Charlie side when they found a male patient, later identified as s.22(1), who appeared to have jumped from the 3rd floor and sustained severe injuries from the fall. The fire crew transported the patient to Cordova St, where they met BCAS.

Fire Investigations arrived on scene during the first alarm assignment. Upon arrival, the scene was highly chaotic with heavy smoke and flames visible from the 3rd floor A/B corner. Investigations immediately started documenting the scene with digital photos and witness interviews.

Fire investigators interviewed s.22(1), occupants from unit # s.22(1). They reported that they noticed smoke coming into their unit and attempted to leave through the hallway. When they opened the door, they found the hallway was full of black smoke and very hot. Fire crews from VAL01 rescued them through their window.

Fire investigators interviewed s.22(1), Winters Residence Manager. s.22(1) stated that the building had a fire on Friday, April 8th. s.22(1) declared that the Winters hotel was under a 24hr Fire Watch order and front desk staff performed regular fire watch patrols every 30mins. It was also reported that fire sprinklers and fire alarm system were not working after the previous fire and they were due to be repaired the day of the April 11th fire. s.22(1) also reported that there were 11 residents unaccounted.

Investigators were alerted that there was a male suffering from smoke inhalation in the north alley of Water Street. s.22(1), a staff member of Winter Residence, was found in the back alley and was



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

complaining of mild smoke inhalation. While awaiting the arrival of BCAS, investigators interviewed s.22(1)

s.22(1) stated that he, and another resident, s.22(1), tried to extinguish a fire in unit#206, which is where he believes the fire started. Due to the fact that the fire extinguishers were still empty from the fire on April 8th. s.22(1) was unsuccessful in extinguishing the fire.

s.22(1) occupies unit #206.

VRE07 and VP06 crews rescued a female trapped on the 1st floor A/B corner with a ground ladder. Name and condition of the person are unknown.

1211hrs- emergency radio traffic was declared, no fire crews to enter the building and defensive firefighting efforts only.

Flames and smoke were now visible from all 3rd floor windows, and the fire had breached the roof.

On an interview with s.22(1) on April 14, 2022, s.22(1) described that he found the door to unit #206 was open slightly. When he opened the door, heavy black smoke and heat came out of the room. s.22(1) using a pressurized water canister, attempted to extinguish the fire. Due to heavy smoke and heat, s.22(1) was unable to continue fighting the fire. He dropped the empty canister outside the door of unit #206. s.22(1) stated that there were no fire alarms activated during the fire. s.22(1) informed investigators that a week prior to the fire, he found 20-40 candles on a plate burning on the floor of unit# 206. He then informed s.22(1) that she could not have burning candles in her room. During the fire, s.22(1) looked inside the room and to the right of the door he noticed a melted pool of wax on the floor, where he noticed the candles burning the week before.

On April 27, 2022, Investigations interviewed s.22(1) from unit# 206. Interviewed her at her new residence at the Arco Hotel. s.22(1) stated that she left the Winters Hotel between 0930-1000hrs. Video evidence shows s.22(1) leaving her room at 1046hrs. s.22(1) stated that she is a smoker s.22(1) also described that she uses tea light candles for lighting cigarettes and smoking narcotics. s.22(1) stated that it was possible that she left an unattended burning candle when she left her unit. Investigations observed several unlit tea candles on s.22(1) bed during the interview.

On May 8, 2022, Investigations interviewed s.22(1). Video footage From April 11th, revealed s.22(1) as one of the people who attempted to fight the fire and alerting the people in the building. s.22(1)





## Vancouver Fire and Rescue Services

### Incident Report

**Case # 220017809**      **CAD Event # E221010116**      **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

s.22(1) became aware of the fire when he heard a person yelling. He looked up and saw a window to unit #206 break, and observed smoke and fire coming out. s.22(1) attempted to retrieve a fire extinguisher but the ones he found were already discharged from the fire on April 8th, 2022. He then found a 5-gallon pail, filled it with water, and ran to the door of unit #206. When s.22(1) opened the door, he observed flames on a bed and up the wall near the South/East corner of unit #206. s.22(1) attempted to throw water onto the fire from the door. These events were confirmed with the video footage. When he was unsuccessful with fighting the fire, he then went around the building alerting people of the fire.

May 19, 2022, a follow up interview was conducted with s.22(1) at the Arco Hotel at 83 W. Pender Street. s.22(1) assisted Fire Investigations with creating a drawing of the layout of her room at the Winters Hotel. During the interview, s.22(1) disclosed that she had set her hair on fire twice while in bed a couple weeks before the fire. Tea light candles left burning on her bed were the cause these fires. The fire investigator asked s.22(1) if she had had any fires on her bed in her current residence, which she informed that she had. There was a visible burn on her bed, and investigations photographed it for documentation.

Due to the structural instability of the building, as determined by Incident Command and Vancouver City Building Department, Fire Investigations was unable to enter the building to conduct a scene examination. This investigation was conducted through witness interviews, security video footage, and visual examinations from elevated locations.

Video evidence and witness interviews suggest that the area of origin to be in the South/East corner of Unit #206.

During the investigation, multiple hypotheses were developed. The possibility of an electrical fire was ruled out, as the only electrical source was on the opposite side of the reported area of origin and there were no devices reported to be plugged in at the time of the fire.

The possibility of an incendiary fire was considered, but after reviewing video evidence from the time of the fire, the timeline and s.22(1) behavior on camera did not support that hypothesis.

Based on evidence available at the scene and witness interviews suggests an ACCIDENTAL fire. There is probable cause to support that unattended candles left on the occupant's bed caused this fire. The candles acted as the competent ignition source, which resulted in heating the bed mattress to its ignition temperature and spreading upward and outward to other combustibles materials scattered throughout the unit.

This was a very complicated fire scene. Upon arrival of the fire crews, they were faced with multiple imminent rescues on the Alpha and Charlie side of the building. In addition to the fire suppression systems



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

not functioning, this building was constructed with no fire stops, cocklofts, a deactivated elevator shaft, and open mezzanines from the 1st to 3rd floor. This allowed the fire to travel unimpeded throughout the structure very quickly. Due to the fire that occurred on April 8th, there were fans placed around the 1st and 2nd floors, which were running at the time of the fire. All these factors combined, created a fire dynamic that was extremely challenging to control.

The remains <sup>s.22(1)</sup> were discovered during the careful and monitored demolition of the building. The remains of <sup>s.22(1)</sup> were located in the area of Unit #204. Due to the fire consuming the floor of Unit# 304, <sup>s.22(1)</sup> remains had fallen to the floor below. The remains of <sup>s.22(1)</sup> were located in the hallway just outside of her unit. #303. <sup>s.22(1)</sup> reported to fire investigators that he last time he saw <sup>s.22(1)</sup> . she was right behind him before he climbed out the window to escape. <sup>s.22(1)</sup> travelled a few feet past her door into the hallway where she was found.

Damage to the structure was extensive and the building which was of heritage status, was a total loss. The human toll was also extensive with several injuries and two fatalities, and dozens of residents and multiple businesses displaced.

The scene was left in care of the City of Vancouver, Chief Building Official, Saul Schwebs.

### Occupants:

<sup>s.22(1)</sup>

### Deceased Occupants:



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809**    **CAD Event # E221010116**    **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

s.22(1)  
[Redacted]

Winters Residence Manager: s.22(1)  
Winters Residence Staff: s.22(1)

Businesses:  
104 Water St.  
Australian Boot Store  
s.22(1)  
s.22(1)

102 Water St. (Flying Pig Restaurant)  
s.22(1)  
s.22(1)

104 Water St. (Australian Boot Store)  
s.22(1)  
s.22(1)

205 Abbott St. (Nika)  
s.22(1)

207 Abbott St. (Roldorf & Co.)  
s.22(1)

209 Abbott St. (Lemongrass House)  
s.22(1)



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

219 Abbott St. (Bruce Eyewear)

s.22(1)

221 Abbott St. (Gowon Café)

Fire Investigator  
Lt. La Greca, Jason (VFRS#6183)

### Injuries

**Casualty Type** Civilian

**Gender** s.22(1)

**Birthdate**

**Telephone**

**Address** s.22(1) - 203 Abbott St.

**City** Vancouver

**Postal**

**Nature of Casualty** 1 s.22(1)

**Date of Death** 04/11/2022

**Status of Casualty** 10 Condition of casualty unknown

**Action of Casualty** 21 Injured while escaping

**Ignition of Clothing** 30 Not applicable OR asphyxiated

**Sleep Wear** 40 Not applicable

**Cause Failure to Escape** 52 Trapped-horiz fire/smoke spread

**Cause of Injury** 100 Smoke Inhalation



# Vancouver Fire and Rescue Services

## Incident Report

**Case #** 220017809    **CAD Event #** E221010116 **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

**Casualty Type** Civilian

**Gender** s.22(1)  
**Birthdate**  
**Telephone**  
**Address** s.22(1) - 203 Abbott St.  
**City** Vancouver  
**Postal**

**Nature of Casualty** 1 s.22(1)  
**Date of Death** 04/11/2022  
**Status of Casualty** 12 Bedridden/other phys handicap  
**Action of Casualty** 20 Action / Activity of Cas.unknow  
**Ignition of Clothing** 30 Not applicable OR asphyxiated  
**Sleep Wear** 40 Not applicable  
**Cause Failure to Escape** 50 Unknown  
**Cause of Injury** 100 Smoke Inhalation

**Casualty Type** Civilian

**Gender** s.22(1)  
**Birthdate**  
**Telephone**  
**Address** s.22(1) -203 Abbott St.  
**City** Vancouver  
**Postal**

**Nature of Casualty** 4 s.22(1)  
**Date of Death**  
**Status of Casualty** 14 Awake/no phys/mental impairment  
**Action of Casualty** 21 Injured while escaping  
**Ignition of Clothing** 30 Not applicable OR asphyxiated  
**Sleep Wear** 40 Not applicable  
**Cause Failure to Escape** 52 Trapped-horiz fire/smoke spread  
**Cause of Injury** 104 Injury caused by falls

### CAD/Dispatch Notes

### LocationComments

20220411105738PD \*\* LOI search completed at 04/11/22 10:57:38 911003706 icad93prodsq1  
20220411105741PD \*\* Cross Referenced to Event # B221010097 at: 04/11/22 10:57:41 0 icad93prodcomm1  
20220411105741PD \*\* >>>> by: on terminal: icad93prodcomm1 0 icad93prodcomm1  
20220411105746PD t: 6va 911002108 ecmfd01  
20220411105746PD \*\* LOI information for Event # E221010116 was viewed at: 04/11/22 10:57:46 VAF 911003154 ecmfd06  
20220411105746PD \*\* >>>> by: JOANNA NGUYEN on terminal: ecmfd06 VAF 911003154 ecmfd06  
20220411105751PD \*\* Case number 220017809 has been assigned to event E221010116 911002108 ecmfd01



# Vancouver Fire and Rescue Services

## Incident Report

---

Case #	220017809	CAD Event #	E221010116	CAD Type	RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE
20220411105751PD	** >>>>	by: 911002108	on terminal: ecmfd01	911002108	ecmfd01
20220411105751PD	**	Recommended unit VAL02	for requirement LADDER (2.1 min)	VAF 911002108	ecmfd01
20220411105751PD	**	Recommended unit VAL08	for requirement LADDER (3.7 min)	VAF 911002108	ecmfd01
20220411105751PD	**	Recommended unit VAE01	for requirement ENGINE (4.4 min)	VAF 911002108	ecmfd01
20220411105751PD	**	Recommended unit VAL01	for requirement LADDER (4.4 min)	VAF 911002108	ecmfd01
20220411105751PD	**	Recommended unit VAM23	for requirement MEDIC-Standalone (2.1 min)	VAF 911002108	ecmfd01
20220411105751PD	**	Recommended unit VAB3	for requirement BATTALION CHIEF (3.7 min)	VAF 911002108	ecmfd01
20220411105814PD	CALLER D/C...	U/K FLOOR	911003706	ecmfd09	
20220411105829PD	**	LOI information for Event # E221010116	was viewed at: 04/11/22 10:58:29	VAF 911002108	ecmfd01
20220411105829PD	** >>>>	by: LESLEY-ANN KERR	on terminal: ecmfd01	VAF 911002108	ecmfd01
20220411105842PD	BOTH WATER STREET AND LANEWAY FIRE ESCAPES ATTACHED TO EXTERIOR OF 203 ABBOTT STREET+	911002108	ecmfd01		
20220411105845PD	FIRE ALARM PULLED	911003706	ecmfd09		
20220411105847PD	BOTH WATER STREET AND LANEWAY FIRE ESCAPES ATTACHED TO EXTERIOR OF 203 ABBOTT STREET	911002108	ecmfd01		
20220411105856PD	ADV TO EVAC.....	911003706	ecmfd09		
20220411105911PD	POSSIBLE 2ND FLOOR	911003706	ecmfd09		
20220411105915PD	CALLER D/C TO GO OUTSIDE	911003706	ecmfd09		
20220411110004PD	**	LOI information for Event # E221010116	was viewed at: 04/11/22 11:00:04	VAF 911003706	ecmfd09
20220411110004PD	** >>>>	by: Ryan O'FLAHERTY	on terminal: ecmfd09	VAF 911003706	ecmfd09
20220411110105PD	**	LOI information for Event # E221010116	was viewed at: 04/11/22 11:01:05	VAF 911002108	ecmfd01
20220411110105PD	** >>>>	by: LESLEY-ANN KERR	on terminal: ecmfd01	VAF 911002108	ecmfd01
20220411110134PD	End of Duplicate Event data	911003706	ecmfd09		
20220411110158PD	2ND CALLER... TROUNCE ALLEY SIDE... TWO PEOPLE HANGING OUT WINDOW....4TH FLOOR	911003706	ecmfd09		
20220411110226PD	ON THE LEDGE.....SITTING ON LEDGE	911003706	ecmfd09		
20220411110233PD	VAB1 -- COPY UPDATE	911002108	ecmfd01		
20220411110244PD	CALLER WILL WAIVE DOWN FD AND GUIDE	911003706	ecmfd09		
20220411110248PD	CALLING EHS	911003320	ecmfd05		
20220411110307PD	EHS WILL UPGRADE	911003320	ecmfd05		
20220411110413PD	End of Duplicate Event data	911003710	ecmfd04		
20220411110416PD	CALLING L08 AT HALL 8	911003320	ecmfd05		
20220411110447PD	End of Duplicate Event data	911003710	ecmfd04		
20220411110519PD	PER HALL 8 L08 IS ENR	911003320	ecmfd05		
20220411110522PD	End of Duplicate Event data	911003061	ecmfd02		



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

20220411110536PD End of Duplicate Event data 911003061 ecmfd02  
20220411110553PD VAB1 -- SECOND ALARM 911002108 ecmfd01  
20220411110614PD \*\* Alarm level updated to 1 VAF 911002108 ecmfd01  
20220411110614PD \*\* Alarm level updated to 2 VAF 911002108 ecmfd01  
20220411110624PD \*\* Recommended unit VAAIR13 for requirement AIR (9.0 min) VAF 911002108 ecmfd01  
20220411110624PD \*\* Recommended unit VAE08 for requirement ENGINE (2.0 min) VAF 911002108 ecmfd01  
20220411110624PD \*\* Recommended unit VAE02 for requirement ENGINE (4.7 min) VAF 911002108 ecmfd01  
20220411110624PD \*\* No recommendation for requirement REHAB SUPPORT or REHAB SUPPORT UNIT VAF 911002108 ecmfd01  
20220411110624PD \*\* No recommendation for requirement DUTY VAF 911002108 ecmfd01  
20220411110624PD \*\* No recommendation for requirement ASSISTANT CHIEF VAF 911002108 ecmfd01  
20220411110630PD End of Duplicate Event data 911003710 ecmfd04  
20220411110702PD End of Duplicate Event data 911003061 ecmfd02  
20220411110703PD CALLING L08 CELL 911003320 ecmfd05  
20220411110731PD VAL08 CELL <sup>s.22(1)</sup> 911003320 ecmfd05  
20220411110738PD NO ANSWER ON L08 CELL 911003320 ecmfd05  
20220411110739PD End of Duplicate Event data 911003710 ecmfd04  
20220411110744PD End of Duplicate Event data 911003706 ecmfd09  
20220411110750PD CALLING HALL 8 911003320 ecmfd05  
20220411110810PD End of Duplicate Event data 911003710 ecmfd04  
20220411110831PD HALL 8 WILL TRY TO GET A HOLD OF L08 911003320 ecmfd05  
20220411110832PD End of Duplicate Event data 911003710 ecmfd04  
20220411110924PD System Unit Alarm VAF 911003706 ecmfd09  
20220411110939PD End of Duplicate Event data 911003710 ecmfd04  
20220411110953PD VAB1 -- ASSUMING CMD 911002108 ecmfd01  
20220411110956PD RMS POLICE ARRIVED SCENE 911003320 ecmfd05  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 VAF 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 VAF 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 911002108 ecmfd01  
20220411111008PD \*\* LOI search completed at 04/11/22 11:08:59 911002108 ecmfd01  
20220411111008PD End of Duplicate Event data 911002108 ecmfd01  
20220411111008PD \*\* Cross Referenced to Event # E221010120 at: 04/11/22 11:10:08 911002108 ecmfd01  
20220411111008PD \*\* >>>> by: LESLEY-ANN KERR on terminal: ecmfd01 911002108 ecmfd01





## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809**      **CAD Event # E221010116** **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

20220411111016PD VAB1 -- THIRD ALARM 911002108 ecmfd01  
20220411111029PD End of Duplicate Event data 911003710 ecmfd04  
20220411111029PD PER VPD ...ARE ONS 911003320 ecmfd05  
20220411111033PD \*\* Alarm level updated to 3 VAF 911002108 ecmfd01  
20220411111040PD \*\* Recommended unit VAP06 for requirement ENGINE (6.3 min) VAF 911002108 ecmfd01  
20220411111040PD \*\* Recommended unit VAL03 for requirement LADDER (6.6 min) VAF 911002108 ecmfd01  
20220411111040PD \*\* No recommendation for requirement DUTY VAF 911002108 ecmfd01  
20220411111040PD \*\* No recommendation for requirement ASSISTANT CHIEF VAF 911002108 ecmfd01  
20220411111107PD RMS GAS NOTIFIED 911003320 ecmfd05  
20220411111139PD End of Duplicate Event data 911003710 ecmfd04  
20220411111158PD End of Duplicate Event data 911003710 ecmfd04  
20220411111212PD End of Duplicate Event data 911003706 ecmfd09  
20220411111225PD End of Duplicate Event data 911003710 ecmfd04  
20220411111241PD CALLER FROM 188 KEEFER PLACE SMELLING SMOKE AND ASH IN THE AIR... 36TH FLOOR 911003706 ecmfd09  
20220411111249PD End of Duplicate Event data 911003710 ecmfd04  
20220411111249PD TRANSIT DISPATCH NOTIFIED 911003320 ecmfd05  
20220411111304PD End of Duplicate Event data 911003710 ecmfd04  
20220411111326PD FILL INS AS FOLLOWS ...E18 X 2 HALL... E05 X 1 HALL 911003061 ecmfd02  
20220411111327PD End of Duplicate Event data 911003706 ecmfd09  
20220411111340PD System Unit Alarm VAF 911002108 ecmfd01  
20220411111350PD VAAC01 -- ASSUMING CMD.. OPERATIONS MAINTAINED BY B1 911002108 ecmfd01  
20220411111359PD DUTY CHIEF NOTIFIED 911003320 ecmfd05  
20220411111421PD VAAC01 -- UPGRADED TO A THIRD ALARM.. IN TRANSITION AT THIS TIME 911002108 ecmfd01  
20220411111441PD End of Duplicate Event data 911003710 ecmfd04  
20220411111450PD FILL INS ANNOUNCED 911003061 ecmfd02  
20220411111450PD ALARM CO CALLING RE 122 WATER ST... STAFF THINKS ALARM WAS TRIGGERED FROM ABBOT ST FIRE 911003706 ecmfd09  
20220411111509PD CALLING E14 CELL AT CHESS TO CLEAR 911003320 ecmfd05  
20220411111533PD NO ANSWER E14 911003320 ecmfd05  
20220411111535PD End of Duplicate Event data 911003710 ecmfd04  
20220411111625PD End of Duplicate Event data 911003706 ecmfd09  
20220411111648PD VAAC01 -- SET UP STAGING AT CORDOVA & ABBOTT 911002108 ecmfd01  
20220411111648PD CHIEF COOPER NOTIFIED 911003320 ecmfd05  
20220411111813PD VAAC01 -- RIT EST ON ALPHA SIDE 911002108 ecmfd01  
20220411111815PD FILL INS AS FOLLOWS E18 X 2 HALL.... E5 X 1 HALL... E19 X 3 KALL... RE15 X 13 HALL 911003061 ecmfd02





## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

---

20220411111834PD \*\* BCEHS Critical Location Information for B221010097 Changed from " to 'stage point: Cambie/Water' 911000001 icad93prodcomm2

20220411111941PD \*\* BCEHS Critical Location Information for B221010097 Changed from 'stage point: Cambie/Water' to 'stage point: 100 W CORDOVA' 911000001 icad93prodcomm2

20220411112006PD CALLING EHS 911003320 ecmfd05

20220411112012PD VAAC01 -- IMMEDIATE RESCUE.. VIA LADDER ON THE FOURTH FLOOR.. MED 911002108 ecmfd01

20220411112012PD BRANCH ON CORNER OF WATER & ABBOT 911002108 ecmfd01

20220411112033PD EHS ADVISED 911003320 ecmfd05

20220411112041PD VAAC01 -- EHS TO ATTEND WATER & ABBOTT.. E01 IS MEDICAL BRANCH 911002108 ecmfd01

20220411112041PD BRIANNA HAMELWRIGHT... 604 662 6895... CBC NEWS 911003706 ecmfd09

20220411112133PD VAAC01 -- BACK UP ESTABLISHED 911002108 ecmfd01

20220411112212PD LM FOR CHIEF MECHANIC 911003320 ecmfd05

20220411112244PD WATERWORKS ADVISED 911003320 ecmfd05

20220411112324PD VAAC01 -- EHS REQ AT ABBOTT & CORDOVA 911002108 ecmfd01

20220411112348PD EHS ADVISED 911003320 ecmfd05

20220411112351PD VAAC01 -- RESPOND CMD4 TO THIS LOCATION.. CORDOVA & ABBOTT 911002108 ecmfd01

20220411112416PD CALLING HALL 4 TO SEE IF CMD VEH 911003320 ecmfd05

20220411112438PD VACMD4 ADVISED OF FIRE 911003320 ecmfd05

20220411112515PD PUMPING STATION ADVISED 911003320 ecmfd05

20220411112517PD BC HYDRO CALLING... ETA 45 MINS 911003706 ecmfd09

20220411112536PD \*\* BCEHS Critical Location Information for B221010097 Changed from 'stage point: 100 W CORDOVA' to 'stage point: (1 ) 100 W CORDOVA, and (2) Cordova/Abbott' 911000001 icad93prodcomm2

20220411112558PD STREETS AND ENGINEERING ADVISED 911003320 ecmfd05

20220411112621PD End of Duplicate Event data 911003706 ecmfd09

20220411112623PD VAAC01 -- STILL DOING FIRE ATTACK BACK UP & RIT IN THE BLDG.. AWAY 911002108 ecmfd01

20220411112623PD FROM HARMS WAY.. IMMEDIATE RESCUE COMPLETED 911002108 ecmfd01

20220411112638PD VAAC01 -- MEDICAL BRANCH & DIRECTOR IS L01 911002108 ecmfd01

20220411112649PD VAAC01 -- EHS REQ IMMEDIATE 911002108 ecmfd01

20220411112728PD VAAC01 -- TYPE 3 BRICK & MORTAR 200X200.. FIRE APPEARS TO BE ON 911002108 ecmfd01

20220411112728PD FOURTH FLOOR TO ABOUT 1/4 OF FOURTH FLOOR ON THE 911002108 ecmfd01

20220411112728PD ALPHA SIDE 911002108 ecmfd01

20220411112740PD VAAC01 -- NO EXPOSURES AT THIS TIME 911002108 ecmfd01

20220411112747PD End of Duplicate Event data 911003710 ecmfd04

20220411112750PD End of Duplicate Event data 911003706 ecmfd09

20220411112812PD VAIN75 ADVISED BY MESSAGE 911003320 ecmfd05



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809**      **CAD Event # E221010116** **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

20220411112851PD ON HOLD WITH EHS 911003061 ecmfd02  
20220411112941PD VAC87 -- OS.. MECH SUPPORT 911002108 ecmfd01  
20220411113000PD EHS ADVISING 2 UNITS ENR FROM HASTINGS/ABBOT... SECOND FROM KNIGHT/KINGSWAY 911003061 ecmfd02  
20220411113003PD DC MOORE ADVISED - LM ON CELL 911003320 ecmfd05  
20220411113010PD System Unit Alarm VAF 911000000 icad93prodadm  
20220411113046PD EHS UPDATED ON STAGING LOCATIONS AND PTS FROM BUILDING 911003061 ecmfd02  
20220411113108PD System Unit Alarm VAF 911003061 ecmfd02  
20220411113207PD End of Duplicate Event data 911003710 ecmfd04  
20220411113211PD System Unit Alarm VAF 911003706 ecmfd09  
20220411113305PD hydro advised of staging location 911002207 ecmfd07  
20220411113315PD End of Duplicate Event data 911003706 ecmfd09  
20220411113343PD \*\* BCEHS Critical Location Information for B221010097 Changed from 'stage point: (1) 100 W CORDOVA, and (2) Cordova/Abbott' to '2 stage points: (1) 100 W CORDOVA, and (2) Cordova/Abbott' 911000001 icad93prodcomm2  
20220411113410PD End of Duplicate Event data 911003710 ecmfd04  
20220411113427PD fortis advised of staging 911002207 ecmfd07  
20220411113447PD End of Duplicate Event data 911003706 ecmfd09  
20220411113448PD VAB1 -- WHO RESPONDED ON THIRD ALARM 911002108 ecmfd01  
20220411113514PD VAB3 -- WHO RESPONDED ON SECOND ALARM 911002108 ecmfd01  
20220411113641PD End of Duplicate Event data 911003710 ecmfd04  
20220411113651PD System Unit Alarm VAF 911003710 ecmfd04  
20220411113708PD End of Duplicate Event data 911003710 ecmfd04  
20220411113734PD End of Duplicate Event data 911003706 ecmfd09  
20220411113747PD System Unit Alarm VAF 911002207 ecmfd07  
20220411113851PD System Unit Alarm VAF 911003320 ecmfd05  
20220411114119PD VACF10 -- FORTIS ON SCENE 911002207 ecmfd07  
20220411114121PD RMS GAS ARRIVED SCENE 911002207 ecmfd07  
20220411114247PD VAAC01 -- ON ORDERS MAKE A FOURTH ALARM.. 911002108 ecmfd01  
20220411114258PD \*\* Alarm level updated to 4 VAF 911002108 ecmfd01  
20220411114305PD \*\* Recommended unit VAE05 for requirement ENGINE (4.7 min) VAF 911002108 ecmfd01  
20220411114305PD \*\* Recommended unit VAE19 for requirement ENGINE (5.0 min) VAF 911002108 ecmfd01  
20220411114305PD \*\* No recommendation for requirement DUTY VAF 911002108 ecmfd01  
20220411114305PD \*\* No recommendation for requirement ASSISTANT CHIEF VAF 911002108 ecmfd01  
20220411114350PD End of Duplicate Event data 911003706 ecmfd09  
20220411114845PD End of Duplicate Event data 911003710 ecmfd04



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809**      **CAD Event # E221010116** **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

20220411114909PD VAE19 -- STAGING LOCATION? 911003061 ecmfd02  
20220411115111PD 4TH ALARM ANNOUNCED 1148 HOURS 911002207 ecmfd07  
20220411115212PD VAE14 INTO HALL 3 911002207 ecmfd07  
20220411115339PD End of Duplicate Event data 911003706 ecmfd09  
20220411115353PD DANIEL WITH CITY OF VAN EOC WILL CONTACT CHIEF COOPER 911002207 ecmfd07  
20220411115536PD PER CHIEF COOPER.. NO MEDICALS 911002108 ecmfd01  
20220411115541PD VATW10 MOVING TO HALL 19 911002207 ecmfd07  
20220411115549PD VAE22 MOVING FROM HALL 19 TO 7/8 BORDER 911002207 ecmfd07  
20220411115600PD VAB3 -- HYDRO RESPONDING? 911002108 ecmfd01  
20220411115754PD EHS ADVISED 911002108 ecmfd01  
20220411120019PD EHS ADVISED OF NO MEDICALS 911002108 ecmfd01  
20220411120037PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120038PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120038PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120039PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120040PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120042PD Alarm Timer Extended: 0 VAF 911002758 ecmfd03  
20220411120101PD VPD CALLING... GETTING TRANSIT BUS FOR RESIDENTSCAMBIE/CORDOVA 911003706 ecmfd09  
20220411120149PD End of Duplicate Event data 911003706 ecmfd09  
20220411120206PD End of Duplicate Event data 911003706 ecmfd09  
20220411120236PD ESS NOTIFIED 911002207 ecmfd07  
20220411120253PD CHIEF COOPER ADVISED TWO UNITS TO BE STAFFED WITHIN ABOUT AN HOUR 911002108 ecmfd01  
20220411120351PD ESS IS IN TOUCH WITH ATIRA AND THEY HAVE STAFF ON SCENE .... APPROX 70 RESIDENTS TO HOUSE 911002207 ecmfd07  
20220411120629PD EHS ADVISED NOT ATTENDING LIFT ASSISTS OR YELLOW & ORANGE CALLS.. PER CHIEF COOPER NOT ATTENDING AUTOMATIC ALARMS ONLY ALARMS CALLED IN BY RESIDENTS 911002108 ecmfd01  
20220411120857PD VAAC01 -- HAVE BCAS MEET CREWS AT WATER/ABBOTT..WE HAVE AN 911002758 ecmfd03  
20220411120857PD EVACUEE 911002758 ecmfd03  
20220411121102PD EHS ADVISED 911002207 ecmfd07  
20220411121107PD VAAC01 -- EMERGENCY TRAFFIC DECLARED..NO FIRE UNITS TO 911002758 ecmfd03  
20220411121107PD ENTER..DEFENSIVE ONLY 911002758 ecmfd03  
20220411121243PD VAAC01 -- RESPOND ESS FOR UNKNOWN NUMBER OF TENANTS AND A 911002758 ecmfd03  
20220411121243PD COAST MOUNTAIN BUS TO CARRALL/WATER 911002758 ecmfd03  
20220411121325PD TRANSIT ADVISED OF LOCATION 911002207 ecmfd07  
20220411121334PD VAAC01 -- COAST BUS IS FOR POSSIBLY DISPLACED TENANTS TO ADJACENT 911002758 ecmfd03



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

---

20220411121334PD BUILDING 911002758 ecmfd03  
20220411121402PD Device 42521/Radio Alias/Default System added. VAF 128014775 \$VACMD4  
20220411121402PD Device 42621/Radio Alias/Default System added. VAF 128014775 \$VACMD4  
20220411121402PD Device 42625/Radio Alias/Default System added. VAF 128014775 \$VACMD4  
20220411121402PD New equipment list for Unit [VACMD4] : VAF 128014775 \$VACMD4  
20220411121402PD Device 000370D2/MDT/Default System added for employee 128014775. VAF 128014775 \$VACMD4  
20220411121402PD Tracking device 000370D2/MDT/Default System set. VAF 128014775 \$VACMD4  
20220411121402PD Tracking device 000370D2/MDT/Default System set for employee 128014775. VAF 128014775 \$VACMD4  
20220411121500PD TRANSIT ADVISED FOR SECOND BUS TO HOUSE RESIDENTS OF ADJACENT BUILDING 911002207 ecmfd07  
20220411121944PD VAAC01 -- HYDRO AND GAS SHUT OFF 911002758 ecmfd03  
20220411122503PD VAAC01 -- BUILDING ON THE WEST SIDE HAS BEEN EVACUATED 911002758 ecmfd03  
20220411124349PD VARE04 - UNABLE TO REACH VIA CELL PHONE 911002207 ecmfd07  
20220411124355PD VPD...HAVE WE CALLED OUT CITY DISASTER TEAM FOR HOUSING?..ADVISED WE CONTACTED ESS AND THE Y WILL DEAL DIRECTLY WITH ATIRA MANAGEMENT 911003320 ecmfd05  
20220411124846PD VAINV75 -- I'M ON SCENE 911002758 ecmfd03  
20220411125313PD VAAC01 -- UPDATE..MAKING ENTRY FROM ALPHA/DELTA CORNER TO GET 911002758 ecmfd03  
20220411125313PD DOCUMENTS..EST A RIT TEAM FOR PROTECTION 911002758 ecmfd03  
20220411125449PD End of Duplicate Event data 911003706 ecmfd09  
20220411125540PD End of Duplicate Event data 911003706 ecmfd09  
20220411130237PD VAB3 -- BELLS RINGING IN 210 ABBOTT..FROM THE SMOKE FROM THIS 911002758 ecmfd03  
20220411130237PD FIRE 911002758 ecmfd03  
20220411130252PD VAB3 -- NO RESPONSE REQUIRED 911002758 ecmfd03  
20220411130404PD End of Duplicate Event data 911003706 ecmfd09  
20220411130450PD VAAC01 -- ALL CREWS HAVE EXITED THE BUILDING 911002758 ecmfd03  
20220411135859PD VAAC01 -- CITY SEWER TO COME DOWN HERE..LOTS OF WATER BUILDING 911002758 ecmfd03  
20220411135859PD UP 911002758 ecmfd03  
20220411140022PD COV SEWERS ADVISED 911002207 ecmfd07  
20220411140320PD End of Duplicate Event data 911003710 ecmfd04  
20220411141814PD VAAC01 -- RESPOND B2 TO THIS LOCATION? 911002758 ecmfd03  
20220411141843PD VAAC01 -- CX REQUEST..WILL CALL IN 911002758 ecmfd03  
20220411141926PD VAAC01 -- DO WE HAVE A CONTACT FOR 112 WATER STREET? 911002758 ecmfd03  
20220411142143PD VPD CHECKING CONTACT INFO FOR 112 WATER SGT 911002207 ecmfd07  
20220411142154PD VACF15 -- I'M OS..CONFIRM RESPONSE FOR CITY..GETTING FLOODED 911002758 ecmfd03  
20220411142154PD PARKADES AND WATER INTO OTHER AREAS 911002758 ecmfd03  
20220411142223PD VACF15 -- HAVE THEM REPORT TO STAGING ABBOTT AND CORDOVA..POSS 911002758 ecmfd03





## Vancouver Fire and Rescue Services

### Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

20220411142223PD A VAC TRUCK WILL BE NEEDED TO CLEAN UP PARKADES 911002758 ecmfd03  
20220411142310PD CITY OF VANCOUVER TO HYDRO VAC ON THE WAY .... WILL REPORT TO STAGING .... 10 MINS 911002207 ecmfd07  
20220411142402PD VAAC01 -- MSG RCD 911002758 ecmfd03  
20220411142921PD VAAC01 -- HAVE VPD GO TO SOUTH ALLEY..LOOTING GOING ON 911002758 ecmfd03  
20220411142958PD VPD ADVISED 911002108 ecmfd01  
20220411143127PD VAB2 -- TAC CHANNEL? COPY, TAC 6 911002758 ecmfd03  
20220411143647PD VAAC01 -- MAYBE TRY ON WATER STREET FROM THE WEST 911002758 ecmfd03  
20220411143716PD VAAC01 -- FOR THE VAC TRUCK TO ACCESS 911002758 ecmfd03  
20220411150751PD End of Duplicate Event data 911003710 ecmfd04  
20220411150815PD FR is NOT responding 911003710 ecmfd04  
20220411153014PD ABBOTT COMMAND VAF 911002207 ecmfd07  
20220411153249PD VAB2 -- RELEASE L08 911002207 ecmfd07  
20220411153708PD VAAC01 -- FIRE STILL SHOWING.. STILL CHASING THE FIRE.. TRYING TO 911002108 ecmfd01  
20220411153708PD RELEASE SOME APPARATUS 911002108 ecmfd01  
20220411161957PD VAB2 -- L03 OUT OF SERVICE MECHANICAL AND GOING TO SHOP 911002207 ecmfd07  
20220411163012PD /NA/ VAF 911002207 ecmfd07  
20220411163059PD VAAC01 -- STANDING DOWN RIT..PACKING SOME OF THE HOSE 911002758 ecmfd03  
20220411163059PD UP..LEAVING SOME APPARATUS FOR ANOTHER FEW HOURS 911002758 ecmfd03  
20220411163219PD VAAC01 -- CONTACT L03 AND HAVE THEM CALL MY CELL 911002758 ecmfd03  
20220411163544PD CALLING L03 CELL <sup>s.22(1)</sup> 911003320 ecmfd05  
20220411163738PD CALLING MACHINE SHOP TO FIND L03 <sup>s.22(1)</sup> ..STATING L03 NOT THERE YET...WILL ADVISE L03 TO CALL DISPATCH 911003320 ecmfd05  
20220411163944PD VAB2 -- RELEASING RE04 911002758 ecmfd03  
20220411163957PD PER CF TOM COOPER ..STILL YELLOW AND ORANGE CALLS AND ALARM CALLS ON HOLD UNTIL FURTHER NOTICE 911003320 ecmfd05  
20220411164508PD VAB2 -- RELEASING E05 IN ABOUT 5 MIN 911002758 ecmfd03  
20220411165338PD VAC87 -- RELEASED FROM SCENE 911002758 ecmfd03  
20220411171325PD VACF2 -- CLEARING THE SCENE 911002758 ecmfd03  
20220411171501PD VAB2 -- CONTACT BCAS..HAVE STANDBY CAR STAND DOWN 911002758 ecmfd03  
20220411171517PD EHS ADVISED 911002207 ecmfd07  
20220411171751PD CHIEF COOPER ADVISED VAFRS WILL RESPOND TO MEDICAL CALLS AND ALARMS AGAIN 911002207 ecmfd07  
20220411171804PD EHS CHARGE DISPATCHER UPDATED 911002207 ecmfd07  
20220411172046PD PER CMD CF MORISHITA OVER PHONE - FIND A DIFFERENT FILL IN FOR HALL 2 AS E18 NEEDS TO GO BACK TO 18 HALL SO THAT L18 AND L03 CAN GO ON A PRIORITY DRILL AT 1800HRS 911003320 ecmfd05



## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

---

20220411172116PD VAAC01 -- CONTACT L03 AND HAVE THEM CALL ON CELL 911002758 ecmfd03  
20220411172234PD VAE14 CLEARING HALL 4 ..GOING TO FILL IN HALL 2 911002207 ecmfd07  
20220411172240PD VAL03 911002758 ecmfd03  
20220411172317PD VAE14 TO GO RELIEVE E18 AT 2 HALL 911002758 ecmfd03  
20220411172345PD VAB2 -- WE'LL BE SENDING RE07 BACK HOME 911002758 ecmfd03  
20220411173827PD VAE02 -- CLEAR, BUT REMAIN ATTACHED UNTIL DECON FINISHED 911002758 ecmfd03  
20220411173930PD VAB2 -- RELEASING B3 AND THEN TERMINATING ISO 911002758 ecmfd03  
20220411174404PD VAP06 -- CLEAR OF CALL..BACK IN DISTRICT..REMAIN ATTACHED FOR 911002758 ecmfd03  
20220411174404PD DECON 911002758 ecmfd03  
20220411174419PD DECONNING VAF 911002758 ecmfd03  
20220411174848PD CHIEF MORISHITA ADVISED TO SEND VATW10 TO THE FIRE TO ASSIST WITH COV OFFICIALS AT 0730 AM 911002207 ecmfd07  
20220411175049PD VAB2 -- RELEASING E08 AND L08, M23 AND AIRLIGHT IN ABOUT 10 911002758 ecmfd03  
20220411175049PD MINUTES 911002758 ecmfd03  
20220411175338PD VAE08 -- E08 AND L08 RELEASED 911002758 ecmfd03  
20220411175441PD VAE08 -- RELEASE FILL IN 911002758 ecmfd03  
20220411180845PD VAAC01 -- SOUTH ALLEY IS NOW ENERGIZED BY HYDRO 911002758 ecmfd03  
20220411181622PD VAAC01 -- RESPOND RE04 TO THE SCENE ROUTINE TO PICK UP COMMAND 911002758 ecmfd03  
20220411181622PD VEHICLE 911002758 ecmfd03  
20220411182748PD DECONNING AT HALL VAF 911002758 ecmfd03  
20220411182754PD DECONNING AT HALL VAF 911002758 ecmfd03  
20220411185612PD VAINV75 -- CLR OF SCN .. AQ 911002499 ecmfd03  
20220411190655PD \*\* LOI information for Event # E221010116 was viewed at: 04/11/22 19:06:55 VAF 911002499 ecmfd03  
20220411190655PD \*\* >>>> by: SEAN STAPLES on terminal: ecmfd03 VAF 911002499 ecmfd03  
20220411192543PD VAL22 -- RESP TO FIRE SCN 911002499 ecmfd03  
20220411192801PD VATW10 -- COPY UPDATE FROM B2 .. RTQ .. 911002499 ecmfd03  
20220411193149PD System Unit Alarm VAF 911003688 ecmfd05  
20220411193747PD VAB1 -- VARIOUS LADDERS WILL COME BY AND SWAP OUT 911003306 ecmfd07  
20220411193747PD CREWS...FROM 19:00-22:00 L15 & L22 TO ATTEND...22:00 - 911003306 ecmfd07  
20220411193747PD 01:00 WILL BE L05 AND L07....01:00 - 04:00 WILL BE L08 AND 911003306 ecmfd07  
20220411193747PD TW10....04:00-07:00 WILL BE L03 AND L18 911003306 ecmfd07  
20220411193835PD VAB1 -- ALL LADDER UNITS ARE AWARE 911003306 ecmfd07  
20220411195211PD VAB2 -- CLR OF EVENT .. RTQ 911002499 ecmfd03  
20220411200008PD VAL15 -- NOW OS TO RELIEVE L01 911002499 ecmfd03  
20220411200043PD VAAC01 -- RESP M23 ROUTINE TO THE SCENE 911003306 ecmfd07



## Vancouver Fire and Rescue Services

### Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

20220411200307PD VAM23 -- COPY ROUTINE 911002499 ecmfd03  
20220411200510PD VAAC01 -- CONTACT FOR 112 WATER ST? 911002499 ecmfd03  
20220411200557PD CA 911002373 ecmfd01  
20220411200616PD CALLING VAN FIRE AND RADIUS AS THEY ARE THE ALARM CO FOR 112 WATER ST 911002373 ecmfd01  
20220411200702PD VAN FIRE WILL MAKE SOME CALLS AND CALL US BACK 911002373 ecmfd01  
20220411200929PD VAAC01 -- COPY RE PR FOR 112 WATER ... TRYING TO GAIN ACCESS 911002499 ecmfd03  
20220411200929PD THROUGH A DOOR LOCK TO 112 WATER .. 911002499 ecmfd03  
20220411201057PD PR ADVISED...ETA 30 MIN AWAY 911003688 ecmfd05  
20220411201127PD VAAC01 -- COPY PR 911002499 ecmfd03  
20220411201159PD VAL02 -- CLR OF SCN .. REMAIN ON EVENT FOR DECON 911002499 ecmfd03  
20220411202244PD VAL01 -- CLEAR...REMAINING ATTACHED TO THE CALL FOR DECON 911003306 ecmfd07  
20220411205726PD VAAC01 -- AC01 STANDING DOWN CMD TX TO B1 .. 911002499 ecmfd03  
20220411205730PD VAB1 -- RMS COMMAND ASSUMED 911002499 ecmfd03  
20220411213013PD VAL05 -- RESPONDER TO TAKEOVER FOR A LADDER 911002499 ecmfd03  
20220411215041PD Relocate Back Unit - Relocate Back Unit VAF 911002499 ecmfd03  
20220411215255PD VAL15 -- ONLY VAB1 REMAIN HERE AND JUST ABOUT TO CLEAR.. ALL 911002499 ecmfd03  
20220411215255PD OTHER CHFS CLEARED 911002499 ecmfd03  
20220411215802PD VAL07 -- RESP TO TAKEOVER FOR FIREWATCH 911002499 ecmfd03  
20220411222041PD System Unit Alarm VAF 911003711 ecmfd04  
20220411225117PD VAB2 -- RESP BACK TO SCN 911002499 ecmfd03  
20220411230321PD Alarm Timer Extended: 0 VAF 911002499 ecmfd03  
20220411233702PD PER B2...TW10 TO STAND DOWN FROM THEIR COVERAGE FROM 01:00-04:00...L03 TO STAND DOWN FROM TH  
EIR COVERAGE FROM 04:00-07:00 911003306 ecmfd07  
20220411233844PD TW10 ADVISED 911003306 ecmfd07  
20220411234857PD \*\* LOI information for Event # E221010116 was viewed at: 04/11/22 23:48:57 VAF 911003688 ecmfd05  
20220411234857PD \*\* >>>> by: JENNIFER FITZGIBBON on terminal: ecmfd05 VAF 911003688 ecmfd05  
20220411234904PD \*\* LOI information for Event # E221010116 was viewed at: 04/11/22 23:49:04 VAF 911003688 ecmfd05  
20220411234904PD \*\* >>>> by: JENNIFER FITZGIBBON on terminal: ecmfd05 VAF 911003688 ecmfd05  
20220412003116PD VAL07 -- CLEAR...RTQ 911003306 ecmfd07  
20220412005158PD VAL08 -- ER...COPY...WILL ACCESS LOCATION OFF WATER ST 911003306 ecmfd07  
20220412024525PD Tracking device 000370EF.U/GPS Device/Default System cleared. VAF 128015087 \$VAL08  
20220412024525PD Device 000370EF.U/GPS Device/Default System removed. VAF 128015087 \$VAL08  
20220412024525PD Device 42542/Radio Alias/Default System removed. VAF 128015087 \$VAL08  
20220412024525PD Device 42542/Radio Alias/Default System added. VAF 128015087 \$VAL08  
20220412024525PD Device 000370EF.U/GPS Device/Default System added. VAF 128015087 \$VAL08



# Vancouver Fire and Rescue Services

## Incident Report

**Case # 220017809 CAD Event # E221010116 CAD Type RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE**

20220412024525PD New equipment list for Unit [VAL08] : VAF 128015087 \$VAL08  
20220412034429PD VAL18 -- RESP TO TAKEOVER FIREWATCH... COPY ACCESS VIA WATER ST 911002499 ecmfd03  
20220412042332PD VAL08 -- CLRD BY L18 .. RTQ .. 911002499 ecmfd03  
20220412073325PD TW10 TO CALL CHIEF BOONE s.22(1) ... AND STAGE TO ABBOT/CORDOVA 911003706 ecmfd09  
20220412073409PD VATW10 -- COPY... HALF A BLOCK AWAY 911003061 ecmfd03  
20220412074926PD VAL18 -- RTQ 911003061 ecmfd03  
20220412075709PD MANAGER OF HOTEL LOOKING TO MEET WITH CHIEF- s.22(1) (CALL BACK) 911003710 ecmfd04  
20220412075719PD End of Duplicate Event data 911003710 ecmfd04  
20220412075940PD MANAGER OF HOTEL WILL HEAD TO WATER & ABBOTT.. WAS PROVIDED CHIEF BOONES CELL NUMBER 911002108 ecmfd01  
20220412080512PD PER CHEIF BERTUZZI HAVE A MEDIC RESPOND TO ABBOT & WATER TO INVEST ALARM AT 112 WATER ENTER FROM THE WEST SIDE.. 911002108 ecmfd01  
20220412080819PD System Unit Alarm VAF 911002108 ecmfd01  
20220412081316PD \*\* LOI information for Event # E221010116 was viewed at: 04/12/22 08:13:16 VAF 911003710 ecmfd04  
20220412081316PD \*\* >>>> by: Dan ATTRIDGE on terminal: ecmfd04 VAF 911003710 ecmfd04  
20220412081451PD System Unit Alarm VAF 911003061 ecmfd03  
20220412085434PD CHIEF BERTUZZI 12 SHEETS OF PLYWOOD TO 112 WATER STREET 911002108 ecmfd01  
20220412085615PD BOARD UP ETA APPROX 2 HOURS 911002108 ecmfd01  
20220412094941PD CHIEF COOPER WOULD LIKE RE04 ATTACHED & THEN CLEARED FROM THE CALL TO SHOW THEIR ATTENDANCE AT YESTERDAYS FIRE 911002108 ecmfd01  
20220412102543PD VAL07 -- HAVE M23 CALL ON CELL 911003061 ecmfd03  
20220412110653PD VAL03 -- RELIEVING LADDER 7 TO TAKE OVER FIRE WATCH 911001809 ecmfd07  
20220412113625PD System Unit Alarm VAF 911001809 ecmfd07  
20220412113632PD Alarm Timer Extended: 0 VAF 911003061 ecmfd03  
20220412131753PD VAL05 -- ER FOR FIREWATCH 911001809 ecmfd07  
20220412131907PD \*\* LOI information for Event # E221010116 was viewed at: 04/12/22 13:19:07 VAF 911003710 ecmfd04  
20220412131907PD \*\* >>>> by: Dan ATTRIDGE on terminal: ecmfd04 VAF 911003710 ecmfd04  
20220412134748PD System Unit Alarm VAF 911003320 ecmfd06  
20220412151208PD \*\* LOI information for Event # E221010116 was viewed at: 04/12/22 15:12:08 VAF 911003710 ecmfd04  
20220412151208PD \*\* >>>> by: Dan ATTRIDGE on terminal: ecmfd04 VAF 911003710 ecmfd04  
20220412151211PD \*\* LOI information for Event # E221010116 was viewed at: 04/12/22 15:12:11 VAF 911003710 ecmfd04  
20220412151211PD \*\* >>>> by: Dan ATTRIDGE on terminal: ecmfd04 VAF 911003710 ecmfd04  
20220414135419PD INVESTIGATION VAF 911002732 ecmfd03  
20220414135447PD \*\* Event E221010116 has been reopened at: 04/14/22 13:54:47 911002732 ecmfd03  
20220414135447PD \*\* >>>> by: JEFFREY CHERNENKO on terminal: ecmfd03 911002732 ecmfd03





## Vancouver Fire and Rescue Services

### Incident Report

---

**Case # 220017809**      **CAD Event # E221010116** **CAD Type** RESIDENTIAL, COMMERCIAL OR INDUSTRIAL STRUCTURE FIRE

---

20220414135448PD \*\* LOI search completed at 04/14/22 13:54:48 911002732 icad93prodsq1  
20220414135456PD /NA/ VAF 911002732 ecmfd03  
20220414135555PD VAINV73 -- REOPEN EVENT ... OS INVESTIGATING 911002732 ecmfd03  
20220425121319PD ATTACH INV73 VAF 911002373 ecmfd05  
20220425121321PD \*\* Event E221010116 has been reopened at: 04/25/22 12:13:21 911002373 ecmfd05  
20220425121321PD \*\* >>> by: COREY KELSO on terminal: ecmfd05 911002373 ecmfd05  
20220425121321PD \*\* LOI search completed at 04/25/22 12:13:21 911002373 icad93prodsq1  
20220425124449PD VAINV73 -- HANDED EVIDENCE TO VPD --LEAVING SCENE IN CARE OF VAB1 911001994 ecmfd07

#### **CAD Note**

BILLOWING SMOKE OUT WINDOW \*\*\*STAGING CORDOVA & ABBOTT\*\*

*End of Report for Case#: 220017809*

Page 73 of 73